

STRUCTURAL REPAIR OF CONCRETE MEASURING 2 FEET WIDE WITH UP TO 1 FOOT PENETRATION DOWN 1 FOOT ON THE NORTH SIDE OF THE CAISSON NEAREST THE NORTHWEST CORNER OF THE PIER.

EPOXY CRACK INJECTION, 1/8 INCH WIDE, NEAR THE MIDPOINT OF THE NORTH PIER FACE FROM THE TOP OF THE PIER WALL TO THE WATERLINE.

STRUCTURAL REPAIR OF CONCRETE 1.5 FEET WIDE BY 3 INCHES HIGH WITH 4 INCHES PENETRATION ON THE NORTH SIDE OF THE FOURTH CAISSON FROM THE NORTHEAST CORNER OF THE PIER WALL.

STRUCTURAL REPAIR OF CONCRETE 1.5 FEET WIDE BY 2 INCHES HIGH WITH 3 INCHES PENETRATION AT THE INTERFACE OF THE CAISSON AND THE PIER WALL ON THE EAST SIDE OF THE SECOND CAISSON FROM THE NORTHEAST CORNER OF THE PIER WALL

STRUCTURAL REPAIR OF CONCRETE > 5" (2 SF)

STRUCTURAL REPAIR OF CONCRETE ≤ 5" (2 SF)

* NOTE: COST OF THE JACKET WILL BE INCLUDED IN THE PAY ITEM: 'STRUCTURAL REPAIR OF CONCRETE'. SEE SPECIAL PROVISION FOR PILE JACKETING.

> LOCATION 3 IL-43 OVER CHICAGO SANITARY & SHIPPING CANAL S.N. 016-0991

ION 3		F.A. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
PAIR PLANS		VAR.	2013-043BR	СООК	22	17
				CONTRACT	NO. 6	OW97
S STA.	TO STA.		ILLINOIS FED. A	ID PROJECT		