


NOTE:  
 PROVIDE HOLE IN MEDIAN SURFACE FOR WOOD SIGN SUPPORT PLACEMENT  
 EXISTING WOOD SIGN SUPPORT REMOVAL SHALL BE CONSIDERED INCLUDED IN THE COST OF RELOCATING THE SIGN PANEL



FILE NAME = I:\01\jobs\01S2024A\CADD\Road\Sheet\C-510.DWG	USER NAME = Tod00272	DESIGNED - heyen	REVISED -
		DRAWN - pop00275	REVISED -
		CHECKED - heyen	REVISED -
		DATE - 11/03/2009	REVISED -

**STATE OF ILLINOIS  
 DEPARTMENT OF TRANSPORTATION**

**US 66 STRINGTOWN RD INTERSECTION DETAIL**

SCALE: 1"=10' SHEET NO. 2 OF 2 SHEETS STA. TO STA.

F.A. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	01-00001-01-BT	MCLEAN	50	32
C-95-301-10			CONTRACT NO. 91429	
ILLINOIS FED. AID PROJECT				