


PIER 2 BILL OF MATERIAL	UNIT	QUANTITY
STRUCTURAL REPAIR OF CONCRETE > 5"	SQ FT	19
STRUCTURAL REPAIR OF CONCRETE < 5"	SQ FT	3
TEMPORARY SHORING AND CRIBBING	EA .	5

<u>I AL</u>	<u> </u>	
D.L. L.L. IMP. TOTAL	62.6 K 43.5 K 9.7 K 115.8 K	'
PIEF	2	•
SPAI	N 2	
	AM	
TAE	TIONS BLE	



	SOUTH ABU	TMENT B	BILL	OF MATER	IΑ	L	UNIT	QUANTITY
-	STRUCTURAL	REPAIR	OF	CONCRETE	>	5′′	SQ FT	- 8

22 K 36.8 K 11 K 69.8 K L.L. IMP. TOTAL PIER 2 SPAN 3

SN 016-1001 TOTAL BILL OF MATERIAL	UNIT	QUANTITY
STRUCTURAL REPAIR OF CONCRETE > 5"	SQ FT	27
STRUCTURAL REPAIR OF CONCRETE < 5"	SQ FT	3
TEMPORARY SHORING AND CRIBBING	EA	5

STRUCTURAL REPAIR OF CONCRETE > 5"



STRUCTURAL REPAIR OF CONCRETE & 5"

			•
FILE NAME =	USER NAME = midyja	DESIGNED -	REVISED -
o:\projects\d120507\11171@47th.dgn		DRAWN -	REVISED -
•	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED -
·	PLOT DATE = 12/28/2007	DATE -	REVISED -

* TEMPORARY SHORING AND CRIBBING

STATE	OF	ILLINOIS
DEPARTMENT	0F	TRANSPORTATION

LOCATION			16–1001	·····	
		ST	RUCTURA	AL REPAIR	
 CULLI	NO	OF	CHEETS	CTA	

SCALE:

				R.
SHEET	4	OF	4	VAF
TO STA.				FI

	SECTION							COUNTY	TOTAL	SHEET S NO.
วบร	2007-007I							VARIOUS	25	10
								CONTRACT	NO.	60C36
	040 DICT	110		70) 1	MATC	CCD.	410	DDA ICAT		