



WEST ABUTMENT

NOTE: QUANTITIES ARE ESTIMATED. ACTUAL QUANTITIES TO BE DETERMINED BY THE RESIDENT ENGINEER.

 STRUCTURAL REPAIR OF CONCRETE <= 5"

| | | | | | | | | | | | |
|-------------|----------------------|----------------|---------------|---|---|---|--------------------------|---|--------------|-----------|--|
| FILE NAME = | USER NAME = #USER* | DESIGNED - --- | REVISED - --- | STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION | STRUCTURAL REPAIR OF CONCRETE 058-0067 | F.A. - | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. | |
| #FILEL* | | DRAWN - --- | REVISED - --- | | | 72 | D7 BRIDGE REPAIRS 2008-2 | MACON | 31 | 22 | |
| | PLOT SCALE = #SCALE* | CHECKED - --- | REVISED - --- | | | SCALE: _____ SHEET NO. ___ OF ___ SHEETS STA. _____ TO STA. _____ | | FED. ROAD DIST. NO. - ILLINOIS FED. AID PROJECT | | | |
| | PLOT DATE = #DATE* | DATE - ----- | REVISED - --- | | | CONTRACT NO. 74270 | | | | | |