STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION






Photo 25 - Deterioration in member-to-member connections with missing washers.




Photo26 - Rusted Washers.

FOR COLOR PHOTOS WITH BETTER RESOLUTION

CONTACT MAHMOUD ETEMALDI (815)284-5393

PHOTOSHEET 5 OF 5

LONGHOLLOW SCENIC OVERLOOK REST AREA TOWER REPAIRS FAP RT. 301 (U.S RT. 20), SECTION 28-SO-M-1 JODAVIESS COUNTY

Soodan

CHECKED H.T./M.R.

DESIGNED I.L. CHECKED H.T.