

TYPICAL END OF SEAL TREATMENTS

LEGEND:

Structural Repair of Concrete (Depth =< 5")

Structural Repair of Concrete (Depth > 5")

Deck Slab Repair (Partial)

Approach Slab Repair (Partial Depth)

X Plug Existing 6" Dia. Deck Drains

BILL OF MATERIAL


	128 91
C= F+	40
Sq.Ft.	42
Sg.Yd.	2.7
Each	12
Foot	88
_	

** Work shall be performed in accordance with Special Provision Deck Slab Repair (Special)

NOTES:

- 1. Remove the existing preformed joint seals and replace with silicone joint sealer as detailed in Sections A-A and B-B.
- Areas of proposed deck repairs are estimated. Actual type, location and dimensions of deck repairs are to be determined by the Engineer during construction.
- 3. Removal of existing Silicone and Neoprene joint shall be inlcuded in the cost of Silicone Joint Sealer, 1.75".
- Contractor may remove and replace guardrail components to facilitate joint replacement work. Cost included with Silicone Joint Sealer, 1.75".

		1.75''at 50°F (at rt. L's)
	Silicone Joint Sealer, 1.75"	
		Existing Steel P
}		
	Existing '2" x '2"	Backer rod having a diameter
Back of ———————————————————————————————————	Bar to remain, (Typ.)	25% greater than joint opening at the time of installation.
	SECTI	TON A-A



SECTION B-B
Curb Repair SRC ≤ 5"

USER NAME =	DESIGNED -	GMK	REVISED -	
PLOT SCALE =	DRAWN -	GFP	REVISED -	DB STERLIN CONSULTANTS, II 123 N. WACKER DRIVE SUITE 2000
PLOT DATE =	CHECKED -	WPK/GMK	REVISED -	CHICAGO, ILLINOIS 80808 TEL. (312)857-1006 FAX. (312)857-1056
FILE NAME =	DATE -	01/18/2011	REVISED -	

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

	WESTBOUND	I-80	IEPAIR OVER 1 099-00	ROCK	-	CREEK	
0.1 000 00.7							
	SHEET NO S-2	OF 5-6	SHEETS				

	F.A.I. SECTION 80 99 (3&4) RS-4			T	COUNTY	TOTAL SHEE SHEETS NO.	
					WILL	117	90
_					CONTRACT	NO. 6	OM65
	FED. R	OAD DIST. NO. 1	ILLINOIS FED.	AID	PROJECT		***************************************