



Notes:
 Reinforcement bars designated (E) shall be epoxy coated.
 Bars indicated thus 20 x 3-#5 etc. indicates 20 lines of bars with 3 lengths per line.
 Section views drawn "FOR INFORMATION ONLY" to be used as reference for beam repair.
 Remove and Replace or Straighten Repairs (See Repair Details - Sheet 1 of 3)

FOR REFERENCE ONLY

FILE NAME = D468854-shr-cover.dgn	USER NAME = jonesco	DESIGNED - CEJ	REVISED - ---	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	DISTING CROSS SECTIONS	F.A.I. RTE. 74	SECTION (X3-17HB)-2	COUNTY WOODFORD	TOTAL SHEETS 11	SHEET NO. 4
PLOT SCALE = 1/4" = 1'-0" / IN.		DRAWN - CEJ		SCALE: _____ SHEET NO. ___ OF ___ SHEETS STA. _____ TO STA. _____		BEAM REPAIRS		CONTRACT NO. 68854		
PLOT DATE = 1/15/2009		CHECKED - ---				FED. ROAD DIST. NO. 4 ILLINOIS FED. AID PROJECT				
		DATE - ---								

SN. 102-0034
 TR134over I-74