


## Notes:


Hatched areas indicate concrete removal. These areas to be poured after structural repair of concrete is complete for remainder of the pier.

For cap removal over non-repair areas, salvage existing #7 vertical bars. Bars to be cleaned, straightened, and incorporated into new construction. Cost included in cost of Concrete Removal.

For cap removal over repair areas, evaluate the existing #7 vertical bars as outlined in the Structural Repair of Concrete Special Provision.








BILL OF MATERIALS

Bar	No.	Size	Length	Shape
h2(E)	6	#5	21'-10"	
h3(E)	6	#5	17'-10"	
v <sub>5</sub> (E)	82	#5	9′-4″	
u1 (E)	6	#5	11'-9"	
Concrete Removal			CU YD	11
Concrete Structures			CU YD	16
Reinforcement Bars, Epoxy Coated			POUND	1,120

#Start removal at bottom of existing notch detail



STRAND ASSOCIATES, INC.

NO. 22 RIE SHEETS	NO.
74 (57-21B)BR MCLEAN 61	34
SHEETS PIER REPAIR DETAILS (1 OF 4) CONTRACT NO. 7064	541
FED. ROAD DIST. NO. 7 ILLINOIS FED. AID PROJECT	