







Hanson Professional Services Inc.  
 Suite 200, 815 Commerce Drive  
 Oak Brook, Illinois 60523  
 © Copyright Hanson Professional Services Inc. 2008





SECTION	OFFSET FROM PGL ELEVATION (ft)		
	A	B	C
(1) STA 24+90	-0.60	0.00	0.00
(2) STA 25+50	-0.60	0.00	0.36
(3) STA 26+10	-1.20	0.00	0.72



SECTION	OFFSET FROM PGL ELEVATION (ft)		
	A	B	C
(1) STA 34+00	-0.72	0.00	0.72
(2) STA 34+60	-0.36	0.00	0.36
(3) STA 35+20	-0.36	0.00	0.00
(4) STA 35+80	-0.36	0.00	-0.36



SECTION	OFFSET FROM PGL ELEVATION (ft)		
	A	B	C
(1) STA 38+00	-0.36	0.00	-0.36
(2) STA 38+84	0.00	0.00	-0.36
(3) STA 39+68	0.36	0.00	-0.36
(4) STA 40+52	0.72	0.00	-0.72



SECTION	OFFSET FROM PGL ELEVATION (ft)		
	A	B	C
(1) STA 45+10	0.72	0.00	-0.72
(2) STA 45+70	0.36	0.00	-0.36
(3) STA 46+90	-0.36	0.00	-0.36

FOR INFORMATION ONLY