
 Deck Slab Repair (Partial Depth) - 50 SQ. YD.
 Note: Partial Depth Repair shall be achieved by bridge deck hydro-scarification and filled with microsilica concrete overlay. Cast included in "BRIDGE DECK HYDRO-SCARIFICATION 2 1/2" " and "BRIDGE DECK MICROSILICA CONCRETE OVERLAY 2 1/4" "

DECK PATCHING PLAN
IL 106 OVER HADLEY CREEK
SN 075-0004

DESIGNED	KTH
CHECKED	ADL
DRAWN	KTH/BGJ
CHECKED	ADL

KLINGNER & ASSOCIATES, P.C.
 Engineers - Architects - Surveyors
 45 North 21st Street, Barrington, IL
 4300 Park Forest Road, Park Forest, IL
 480 N. Ash Street, Suite 100, Burlington, IL
 411 W. 11th Street, Galesburg, IL
 Internet Address: www.klingner.com
 Ph: (815) 221-3570 Fax: (815) 221-3883
 Ph: (815) 221-0020 Fax: (815) 221-0022
 Ph: (815) 753-9536 Fax: (815) 752-3605
 Ph: (815) 942-4042 Fax: (815) 942-3708
 STATE OF ILLINOIS DESIGN FIRM # 1842738



SHEET NO. 5	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	751	D6 BRIDGE REPAIR 2009	PIKE	22	22
5 SHEETS	CONTRACT NO. 72D44				
FED. ROAD DIST. NO.		ILLINOIS FED. AID PROJECT			