



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION







(Looking Northeast)



BILL OF MATERIAL

Item	Unit	Total
Epoxy Crack Injection	Foot	3 5
Structural Repair of Concrete (Depth Greater Than 5 inches)	Sq. Ft.	8
Structural Repair of Concrete (Depth Equal to or Less Than 5 inches)	Sq. Ft.	25

<u>LEGEND</u>

Structural Repair of Concrete (Depth Greater Than 5 inches)

Structural Repair of Concrete (Depth Equal to or Less Than 5 inches)

Epoxy Crack Injection

PIER NO. 2 REPAIR STRUCTURE NO. 084-0028

NOTE:

Crack widths are $^{l}_{8}$ " ($^{\pm}{}^{l}_{16}$ ") unless otherwise noted.

SHEET NO. B42	F./ RT
44 SHEETS	

42	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
_	55	(84-3HB-6)BR	SANGAMON	90	76
;		SN 084-0028	CONTRACT	NO. 72	A64

FED. ROAD DIST. NO. 6 ILLINOIS FED. AID PROJECT

FARNSWORTH GROUP, INC.

DESIGNED JML

CHECKED MSW

DRAWN DJM

CHECKED MGO/MSW

DATE 03/05/09