



BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Epoxy Crack Injection	Foot	17

NOTES:

- For General Notes and Total Bill of Material, see Sheet S02.
- Quantities and limits shown are estimated for bidding purposes only. The actual areas to be repaired and the type(s) of repairs to be used will be determined by the Engineer in the field at the time of construction.
- The Contractor is responsible to remove, support and reinstall all existing utilities interfering with the work. Cost shall be included with Structural Repair of Concrete (Depth Equal to or Less Than 5").

LEGEND

- Low Pressure Epoxy Injection (Width > 0.06")
- Linear Foot

HBM
ENGINEERING GROUP, LLC
CONSULTING & DESIGN
INSPECTION & TESTING
RESEARCH & TESTING

4415 WEST HARRISON ST.
SUITE 231
HILLSIDE, IL 60162
PHONE: (708) 236-0900
FAX: (708) 236-0901

DESIGNED - HH, JJS
CHECKED - MI
DRAWN - HH

REVISED -
REVISED -
REVISED -
REVISED -

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**PIER 8 REPAIRS
EB US ROUTE 20 OVER PECATONICA RIVER STRUCTURE NO. 089-0042**

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
0301	(177-4B-1)M	STEPHENSON	43	41
CONTRACT NO. 64J24				

SHEET NO. S24 OF S26 SHEETS

ILLINOIS FED. AID PROJECT

DATE - 03/13/2013

CHECKED - MAI, MI
REVISED -