



PLAN
WEST SLOPE WALL REPAIRS




SECTION THRU
SLOPEWALL



SECTION A-A

LEGEND



BILL OF MATERIAL

ITEM	UNIT	TOTAL
Slope Wall Repair	SQ YD	70

Notes:
Slope wall shall be reinforced with welded wire fabric, 6 in. x 6 in., W4.0 x W4.0, weighting 58 lbs. per 100 sq. ft.
Do not pour slope wall of abutments until new wingwalls are constructed.

REV. SHEET 6-3-13

CEC Cummins Engineering Corporation
Civil and Structural Engineering

JOB • 2276.3
FILE • 0540057_0058-28-29-SN0057SlopeWall.dgn
DATE • 5/14/2013

DESIGNED - AAN
CHECKED - MDC
DRAWN - SJS
CHECKED - MDC

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

WEST SLOPE WALL REPAIRS
STRUCTURE NO. 054-0057 (NB) & 054-0058 (SB)

SHEET NO. 28 OF 31 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
55	D6 LOGAN CO BR 2011-1	LOGAN	429	227
CONTRACT NO. 72E11				
ILLINOIS FED. AID PROJECT				