









Slope Wall Repair

## BILL OF MATERIAL

ITEM	UNIT	TOTAL		
Slope Wall Repair	SQ YD	222		
Controlled Low-Strength Material	CU YD	79		

Notes

Slope wall shall be reinforced with welded wire fabric, 6 in. x 6 in., W4.0 x W4.0, weighting 58 lbs. per 100 sq. ft.

Cummins JOB = 2265.2 DESIGNED - AAN REVISED -	STATE OF ILLINOIS	EAST SLOPE WALL REPAIR	F.A.I. SECTION	COUNTY TOTAL SHEET
Engineering FILE = 0540060.0061-72E11-50-51-SlopeGHBGKGD - MDL REVISED -		STRUCTURE NO. 054-0060 (SB) & STRUCTURE NO. 054-0061 (NB)	55 D6 LOGAN CO BR 2011-1	LOGAN 429 281
Corporation DATE = 3/18/2013 DRAWN - SJS REVISED -	DEPARTMENT OF TRANSPORTATION	31NUCTURE NO. 034-0000 (3B) & 31NUCTURE NO. 034-0001 (NB)		CONTRACT NO. 72E11
Civil and Structural Engineering CHECKED - MDC REVISED -		SHEET NO. 51 OF 53 SHEETS	ILLINOIS FED. AI	ID PROJECT