June 7, 2018

SUBJECT: Various Routes

Section 11-00076-00-SW (Lake Zurich)

Lake County

Contract No. 61E81

Item 178

June 15, 2018 Letting

Addendum (B)

NOTICE TO PROSPECTIVE BIDDERS:

Attached is an addendum to the plans or proposal. This addendum involves revised and/or added material.

- 1. Revised BDE Special Provisions Check Sheet.
- 2. Added page 57A to the BDE Special Provisions.

Prime contractors must utilize the enclosed material when preparing their bid and must include any Schedule of Prices changes in their bid.

Very truly yours,

Jack A. Elston, P.E.

Bureau Chief

Engineer of Design and Environment

By: Ted B. Walschleger, P.E.

Tet Deluklye A.E.

Engineer of Project Management

BDE SPECIAL PROVISIONS

The following special provisions indicated by an "X" are applicable to this contract. An * indicates a new or revised special provision for the letting.

N	<u>File</u> Name	<u>Pg.</u>		Special Provision Title	Effective	Revised
-	80099			Accessible Pedestrian Signals (APS)	April 1, 2003	Jan. 1, 2014
	80382			Adjusting Frames and Grates	April 1, 2017	Jan 1, 2011
	80274			Aggregate Subgrade Improvement	April 1, 2012	April 1, 2016
	80192			Automated Flagger Assistance Device	Jan. 1, 2008	
	80173			Bituminous Materials Cost Adjustments	Nov. 2, 2006	Aug. 1, 2017
	80241			Bridge Demolition Debris	July 1, 2009	3 ,
	5026I			Building Removal-Case I (Non-Friable and Friable Asbestos)	Sept. 1, 1990	April 1, 2010
	5048I			Building Removal-Case II (Non-Friable Asbestos)	Sept. 1, 1990	April 1, 2010
	5049I			Building Removal-Case III (Friable Asbestos)	Sept. 1, 1990	April 1, 2010
	5053I			Building Removal-Case IV (No Asbestos)	Sept. 1, 1990	April 1, 2010
	80366			Butt Joints	July 1, 2016	·
	80386			Calcium Aluminate Cement for Class PP-5 Concrete Patching	Nov. 1, 2017	
	80396			Class A and B Patching	Jan. 1, 2018	
	80384	35	Χ	Compensable Delay Costs	June 2, 2017	
	80198			Completion Date (via calendar days)	April 1, 2008	
	80199			Completion Date (via calendar days) Plus Working Days	April 1, 2008	
	80293			Concrete Box Culverts with Skews > 30 Degrees and Design Fills ≤ 5 Feet	April 1, 2012	July 1, 2016
	80311			Concrete End Sections for Pipe Culverts	Jan. 1, 2013	April 1, 2016
	80277			Concrete Mix Design – Department Provided	Jan. 1, 2012	April 1, 2016
	80261	39	Χ	Construction Air Quality – Diesel Retrofit	June 1, 2010	Nov. 1, 2014
	80387			Contrast Preformed Plastic Pavement Marking	Nov. 1, 2017	
*	80029	42	Χ	Disadvantaged Business Enterprise Participation	Sept. 1, 2000	April 2, 2018
	80378			Dowel Bar Inserter	Jan. 1, 2017	Jan. 1, 2018
	80388	53	Χ	Equipment Parking and Storage	Nov. 1, 2017	
	80229			Fuel Cost Adjustment	April 1, 2009	Aug. 1, 2017
	80304			Grooving for Recessed Pavement Markings	Nov. 1, 2012	Nov. 1, 2017
	80246	54	Χ	Hot-Mix Asphalt – Density Testing of Longitudinal Joints	Jan. 1, 2010	April 1, 2016
	80347			Hot-Mix Asphalt – Pay for Performance Using Percent Within Limits - Jobsite Sampling	Nov. 1, 2014	Jan. 1, 2018
	80383			Hot-Mix Asphalt – Quality Control for Performance	April 1, 2017	Nov. 1, 2017
	80376	55	Χ	Hot-Mix Asphalt – Tack Coat	Nov. 1, 2016	
	80392	56	Χ	Lights on Barricades	Jan. 1, 2018	
	80336			Longitudinal Joint and Crack Patching	April 1, 2014	April 1, 2016
*	80393			Manholes, Valve Vaults, and Flat Slab Tops		March 2, 2018
	80045			Material Transfer Device	June 15, 1999	Aug. 1, 2014
*	80394			Metal Flared End Section for Pipe Culverts	Jan. 1, 2018	April 1, 2018
	80165			Moisture Cured Urethane Paint System	Nov. 1, 2006	Jan. 1, 2010
	80349			Pavement Marking Blackout Tape	Nov. 1, 2014	April 1, 2016
	80371	57A	Х	Pavement Marking Removal	July 1, 2016	
	80390	58	Х	Payments to Subcontractors	Nov. 2, 2017	
	80377			Portable Changeable Message Signs	Nov. 1, 2016	April 1, 2017
	80389	59	Х	Portland Cement Concrete	Nov. 1, 2017	
	80359			Portland Cement Concrete Bridge Deck Curing	April 1, 2015	Nov. 1, 2017
	80385	60	Х	Portland Cement Concrete Sidewalk	Aug. 1, 2017	
	80300	0.4		Preformed Plastic Pavement Marking Type D - Inlaid	April 1, 2012	April 1, 2016
	80328	61	Χ	Progress Payments	Nov. 2, 2013	L
	3426I			Railroad Protective Liability Insurance	Dec. 1, 1986	Jan. 1, 2006
	80157			Railroad Protective Liability Insurance (5 and 10)	Jan. 1, 2006	

<u>File</u> Name	Pg.		Special Provision Title	Effective	Revised
80306			Reclaimed Asphalt Pavement (RAP) and Reclaimed Asphalt Shingles (RAS)	Nov. 1, 2012	Jan. 1, 2018
80395			Sloped Metal End Section for Pipe Culverts	Jan. 1, 2018	
80340			Speed Display Trailer	April 2, 2014	Jan. 1, 2017
80127			Steel Cost Adjustment	April 2, 2014	Aug. 1, 2017
* 80397	62	Χ	Subcontractor and DBE Payment Reporting	April 2, 2018	
80391	63	Χ	Subcontractor Mobilization Payments	Nov. 2, 2017	
80317			Surface Testing of Hot-Mix Asphalt Overlays	Jan. 1, 2013	April 1, 2016
80298			Temporary Pavement Marking (NOTE: This special provision was previously named "Pavement Marking Tape Type IV".)	April 1, 2012	April 1, 2017
20338			Training Special Provision	Oct. 15, 1975	
80318			Traversable Pipe Grate for Concrete End Sections (Note: This special provision was previously named "Traversable Pipe Grate".)	Jan. 1, 2013	Jan. 1, 2018
80288	64	Χ	Warm Mix Asphalt	Jan. 1, 2012	April 1, 2016
80302	66	Χ	Weekly DBE Trucking Reports	June 2, 2012	April 2, 2015
80071			Working Days	Jan. 1, 2002	

The following special provisions are in the 2018 Supplemental Specifications and Recurring Special Provisions.

<u>File</u> Name	Special Provision Title	New Location	<u>Effective</u>	<u>Revised</u>
80368	Light Tower	Article 1069.08	July 1, 2016	
80369	Mast Arm Assembly and Pole	Article 1077.03(a)(1)	July 1, 2016	
80338	Portland Cement Concrete Partial Depth Hot-Mix Asphalt Patching	Recurring CS #35	April 1, 2014	April 1, 2016
80379	Steel Plate Beam Guardrail	Articles 630.02, 630.05, 630.06, and 630.08	Jan. 1, 2017	
80381	Traffic Barrier Terminal, Type 1 Special	Article 631.04	Jan. 1, 2017	
80380	Tubular Markers	Articles 701.03, 701.15, 701.18, and 1106.02	Jan. 1, 2017	

PAVEMENT MARKING REMOVAL (BDE)

Effective: July 1, 2016

Revise Article 783.02 of the Standard Specifications to read:

"783.02 Equipment. Equipment shall be according to the following.

Note 1. Grinding equipment shall be approved by the Engineer."

Revise the first paragraph of Article 783.03 of the Standard Specifications to read:

"783.03 Removal of Conflicting Markings. Existing pavement markings that conflict with revised traffic patterns shall be removed. If darkness or inclement weather prohibits the removal operations, such operations shall be resumed the next morning or when weather permits. In the event of removal equipment failure, such equipment shall be repaired, replaced, or leased so removal operations can be resumed within 24 hours."

Revise the first and second sentences of the first paragraph of Article 783.03(a) of the Standard Specifications to read:

"The existing pavement markings shall be removed by the method specified and in a manner that does not materially damage the surface or texture of the pavement or surfacing. Small particles of tightly adhering existing markings may remain in place, if in the opinion of the Engineer, complete removal of the small particles will result in pavement surface damage."

Revise the first paragraph of Article 783.04 of the Standard Specifications to read:

"**783.04 Cleaning.** The roadway surface shall be cleaned of debris or any other deleterious material by the use of compressed air or water blast."

Revise the first paragraph of Article 783.06 of the Standard Specifications to read:

"783.06 Basis of Payment. This work will be paid for at the contract unit price per each for RAISED REFLECTIVE PAVEMENT MARKER REMOVAL, or at the contract unit price per square foot (square meter) for PAVEMENT MARKING REMOVAL – GRINDING and/or PAVEMENT MARKING REMOVAL – WATER BLASTING."

Delete Article 1101.13 from the Standard Specifications.

80371

Added 6/7/18 57A