

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
315	(22B)1-1	HANCOCK	13	4
STA. _____		TO STA. _____		
FED. ROAD DIST. NO. 6		ILLINOIS	FED. AID PROJECT	

REPAIR SCHEDULE				
REPAIR LETTER	LOCATION	DEFICIENCY	REPAIR	PAY ITEM(S)
A	NORTH PARAPET @ EXPANSION JOINT #2 (PIER 2)	CONC. SPALLING AROUND EXPANSION PLATE	REMOVE AND REPLACE PARAPET SECTION	50100705,50157300,50300255,50800205
B	3RD CROSSFRAME EAST OF PIER 3, INSIDE OF NORTH FASCIA GIRDER	1 BOLT MISSING	REPLACE 7/8" BOLT	50501140
C	2ND CROSSFRAME WEST OF PIER 4, BETWEEN SOUTH FASCIA GIRDER AND ADJACENT GIRDER	4 BOLTS MISSING, EACH SIDE	REPLACE 7/8" BOLTS	50501140
D	PIER 5 PROTECTION CELL HANDRAIL	DAMAGED HANDRAIL	REMOVE REMAINING HANDRAIL	50900705
E	PIER 5 PROTECTION CELL CATWALK HANDRAIL	DAMAGED HANDRAIL	REMOVE AND REPLACE HANDRAIL	50900705,50901760
F	FASCIA GIRDER @ 3RD CROSSFRAME EAST OF SPAN 6 SPLICE	2 HOLES IN WEB	FILL HOLES WITH 7/8" BOLTS	50501140
G	SOUTH PEDESTRIAN RAIL, CENTER OF SPAN 9	1 NUT MISSING	REPLACE 3/4" NUT	50501140
H	PIER 9, BEARING UNDER FIRST GIRDER NORTH OF SOUTH FASCIA GIRDER	3 NUTS MISSING	REPLACE 1-1/2" NUTS	50501140
I	NORTH PARAPET @ EXPANSION JOINT #4 (PIER 9)	CONC. SPALLING AROUND EXPANSION PLATE	REMOVE AND REPLACE PARAPET SECTION	50100705,50157300,50300255,50800205
J	PIER 10, BEARING UNDER NORTH FASCIA GIRGER	1 NUT MISSING	REPLACE 1-1/2" NUT	50501140
K	PIER 10, BEARING UNDER FIRST GIRDER SOUTH OF NORTH FASCIA GIRDER	4 NUTS MISSING	REPLACE 1-1/2" NUTS	50501140
L	PIER 10, BEARING UNDER MIDDLE GIRGER	3 NUTS MISSING	REPLACE 1-1/2" NUTS	50501140
M	PIER 10, BEARING UNDER FIRST GIRDER NORTH OF SOUTH FASCIA GIRDER	1 NUT MISSING	REPLACE 1-1/2" NUT	50501140
N	PEDESTRIAN RAIL ON PARAPET, NEAR PIER 12	1 NUT MISSING	REPLACE 5/8" NUT	50501140
O	RETAINER PLATE FOR BEARING UNDER NORTH FASCIA GIRDER. @ EXPANSION JOINT NEAR PIER 12	RETAINER PLATE BOLT MISSING	REPLACE 7/8" THREADED STUD AND NUT	50501140

NOTES:

THE CONTRACTOR SHALL VERIFY BOLT AND NUT SIZES IN THE FIELD PRIOR TO ORDERING MATERIALS.

ANY DAMAGED THREADS ON EXISTING BOLTS OR STUDS SHALL BE REPAIRED PRIOR TO INSTALLING NEW NUTS. THE COST OF THIS WORK SHALL BE INCLUDED IN THE BID PRICE FOR STRUCTURAL STEEL REPAIR.

REVISIONS		ILLINOIS DEPARTMENT OF TRANSPORTATION	
NAME	DATE	SCHEDULE OF REPAIRS	
		FAP 315 (US 136)	
		SECTION (22B)1-1	
		HANCOCK COUNTY	
		VERT. SCALE:	DRAWN BY
		HORIZ. DATE	CHECKED BY