TRANSPORTATION BULLETIN



ADDENDUM NO. 1

Dated: July 27, 2009

For: Transportation Bulletin Volume 12 No. 26r4 Dated: July 9, 2009 Revised: July 22, 2009 Letting Date: July 31, 2009

Item No. 13A
Quad City International Airport
Moline, Illinois
Taxiway P, Phase III – West End Paving
III. Proj. No. MLI-3855
AIP No. 3-17-0068-XX
Contract QU010

REASON FOR ADDENDUM:

The pay item Refurbish Taxi Guidance Sign (AR125984) originally called for refurbishing signs that were to be installed on Project MLI-3854 (Taxiway P, Phase II-Middle Paving), from incandescent signs to LED signs meeting the current FAA standards for constant illumination. Since the time that project MLI-3854 was bid it has been determined that the incandescent signs will be changed to LED signs thus eliminating the need to refurbish them. It has been further determined by FAA that this pay item can be used to change two (2) signs on this project. The special provision describing the work item has been modified to clarify the fact that the refurbished sign will actually be a new LED sign to be installed on an existing sign base.

TO ALL PLAN HOLDERS:

1. <u>SECTION III SPECIAL PROVISIONS FOR TAXIWAY P, PHASE III-WEST PAVING, PAGE 82, SECTION 125-3.10 AR125984 REFURBISH TAXI GUIDANCE SIGN:</u>

ADD: This item shall include all work items that are necessary to remove the existing signs and supply and install new signs with LED lighting systems (including LED lamps and isolation transformers as required by the manufacturer). New signs shall meet the requirements of sections 125-2.16 and 125-3.60. Existing concrete sign bases (extend bases as required for new signs) and splice cans may be reused.

2. <u>CONSTRUCTION PLAN SHEET 47 OF 91, TEMPORARY RUNWAY 10-28 GUIDANCE SIGN PLAN:</u>

DELETE: "Schedule of Existing Guidance Signs to be Refurbished" table.

ADD: Attached "Revised Schedule of Existing Guidance Signs to be Refurbished" table.

The second secon	۵	REVISED SCHEDU (ISTING TRADITIONAL INCANDESCENT	SIZE	XISTING LE 2, CLAS	GUIDANCE S 2 SIGNS T	OF EXISTING GUIDANCE SIGNS TO BE REFURBISHED 3, STYLE 2, CLASS 2 SIGNS TO LED LIGHTING SYSTEM SIGNS WITH LED LAMPS	AMPS
SIGN NUMBER	FACE	EXISTING LEGEND	LETTERS BACKGROUND	CIRCUIT	PAY ITEMS*	LOCATION	REMARK
9-Q	SE	E 235	Y B W R W R Y B B B B B	T-D	W R T-D AR125984	NORTHWEST SIDE OF R5-23 ON EXTG. TAXIWAY D (PROP. T-E)	RETROFIT EXISTING 3 MODULE SIGN
D-7	SE	23 -5 E	WRWRYB BBBKYB	T-D	Y B T-D AR125984	NORTHWEST SIDE OF R5-23 ON EXTG. TAXIWAY D (PROP. T-E)	RETROFIT EXISTING 3 MODULE SIGN

* = THE ARIZE984 - REFURBISH TAXI GUIDANCE SIGN CONTRACT UNIT PRICE SHALL INCLUDE ALL COSTS TO REMOVE THE EXISTING SIGN AND SUPPLY & INSTALL NEW SIGN WITH LED LIGHTING SYSTEMS (INCLUDING LED LAMPS AND ISOLATION TRANSFORMERS AS REQUIRED BY THE MANUFACTURER). EXISTING CONCRETE SIGN BASE (EXTEND BASE AS REQUIRED) AND SPLICE CAN MAY BE REUSED.