TRANSPORTATION BULLETIN



ADDENDUM NO. 1

Dated: July 27, 2009

For: Transportation Bulletin
Volume 12 No. 26r4
Dated: July 9, 2009 Revised: July 22,2009
Letting Date: July 31, 2009

Item No. 8A
Quad City International Airport
Moline, Illinois
Taxiway P, Phase IV – East End Paving
III. Proj. No. MLI-3873
AIP No. 3-17-0068-XX
Contract QU011

REASON FOR ADDENDUM:

The pay item Refurbish Taxi Guidance Sign (AR125984) originally called for refurbishing signs that were to be installed on Project MLI-3854 (Taxiway P, Phase II-Middle Paving), from incandescent signs to LED signs meeting the current FAA standards for constant illumination. Since the time that project MLI-3854 was bid it has been determined that the incandescent signs will be changed to LED signs thus eliminating the need to refurbish them. It has been further determined by FAA that this pay item can be used to change five (5) signs on this project. The special provision describing the work item has been modified to clarify the fact that the refurbished sign will actually be a new LED sign to be installed on an existing sign base.

TO ALL PLAN HOLDERS:

1. <u>SECTION III SPECIAL PROVISIONS FOR TAXIWAY P, PHASE IV-EAST PAVING, PAGE 84, SECTION 125-3.14 AR125984 REFURBISH TAXI GUIDANCE SIGN:</u>

ADD: This item shall include all work items that are necessary to remove the existing signs and supply and install new signs with LED lighting systems (including LED lamps and isolation transformers as required by the manufacturer). New signs shall meet the requirements of sections 125-2.16 and 125-3.70. Existing concrete sign bases (extend bases as required for new sign) and splice cans may be reused.

2. <u>CONSTRUCTION PLAN SHEET 44 OF 74, TEMPORARY RUNWAY 10-28/ TAXIWAY P</u> <u>GUIDANCE SIGN PLAN:</u>

DELETE: "Schedule of Existing Guidance Signs to be Refurbished" table.

3. ADD: Attached "Revised Schedule of Existing Guidance Signs to be Refurbished" table.

REVISED SCHEDULE OF EXISTING GUIDANCE SIGNS TO BE REFURBISHED EXISTING TRADITIONAL INCANDESCENT SIZE 3, STYLE 2, CLASS 2 SIGNS TO LED LIGHTING SYSTEM SIGNS WITH LED LAMPS	REMARK	RETROFIT EXISTING 3 MODULE SIGN	RETROFIT EXISTING 4 MODULE SIGN	RETROFIT EXISTING 2 MODULE SIGN	RETROFIT EXISTING 3 MODULE SIGN	RETROFIT EXISTING 3 MODULE SIGN
	LOCATION	NORTH SIDE OF TAXIWAY K AT TAXIWAYS K4 / K5	NORTH SIDE OF TAXIWAY K AT TAXIWAYS K4 / K5	SOUTH SIDE OF TAXIWAY K AT TAXIWAY K6	SOUTH SIDE OF TAXIWAY K AT TAXIWAY K2	SOUTH SIDE OF TAXIWAY K AT TAXIWAYS K6 / K7
	PAY ITEMS*	-K-2 AR125984	-K-2 AR125984	-K-2 AR125984	T-K-1 AR125984	-K-2 AR125984
	CIRCUIT	T-K-2	T-K-2	T-K-2	T-K-1	T-K-2
	LETTERS BACKGROUND	8 8 8 8 8 8 4 8 4 8 4	B B B B B B B B B B B B B B B B B B B	B B B X X B X B X X B X X B X X B X X B X X B X X B X X B X X B X X B X X B X X B X X B X B X X B X B X X B X B X B X B X X B X B X B X B X X B	B B B B B B B B B B	
	EXISTING LEGEND	← 5 • 9 • 13	31 •27 •23		7	★ ★ ∀ ∀
لعا	FACE	z o	z	z v	≫ ш	z v
	SIGN NUMBER	K5-2	K5-3	K6-1	K-7	K7-1

* = THE AR125984 - REFURBISH TAXI GUIDANCE SIGN CONTRACT UNIT PRICE SHALL INCLUDE ALL COSTS TO REMOVE THE EXISTING SIGN AND SUPPLY & INSTALL NEW SIGN WITH LED LIGHTING SYSTEMS (INCLUDING LED LAMPS AND ISOLATION TRANSFORMERS AS REQUIRED BY THE MANUFACTURER). EXISTING CONCRETE SIGN BASE (EXTEND BASE AS REQUIRED) AND SPLICE CAN MAY BE REUSED.