

A.JK

REVISED

CHECKED -

PLOT DATE = 12/20/2013

holes drilled in the concrete through holes in the bottom bearing plate after members are in place. Side retainers

the elastomeric bearing assembly shall be included in the

The structural steel plates of the bearing assemblies

Item	Unit	Total
Elastomeric Bearing Assembly Type II	Each	9
Anchor Bolts, 34"	Each	18

SHEET NO. SD69 OF

LS 1 OF 2	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.	
D. 016–2457	372	2013-038B-R	СООК	821	444	
		CONTRACT NO. 60J16				
F SD83 SHEETS		ILLINOIS FED. AID PROJECT				