GENERAL NOTES:

- 1. Fasteners shall be ASTM A325 Type 1, mechanically galvanized bolts. Bolts $\frac{3}{4}$ in. dia., open holes ¹⁵₁₆ in. dia., unless otherwise noted.
- 2. Calculated weight of Structural Steel: M 270 Grade 36 = 107,820 pounds M 270 Grade 50 = 1,469,310 pounds
- 3. No field welding is permitted except as specified in the contract documents.
- 4. Reinforcement bars designated (E) shall be epoxy coated.
- 5. If the Contractor elects to use cantilever forming brackets on the exterior girders, the brackets shall be placed at the same locations as required for the hardwood blocks in Article 503,06(b) of the Standard Specifications. If additional cantilever forming brackets are required, hardwood blocking shall be wedged between the exterior and first interior girder at each of these additional bracket locations.
- 6. Bearing seat surfaces shall be constructed or adjusted to the designated elevations within a tolerance of l_{g} in. (0.01 ft.). Adjustment shall be made either by grinding the surface or by shimming the bearings.
- 7. The existing structural steel coating contains lead. The Contractor shall take appropriate precautions to deal with the presence of lead on the project.
- 8. The Inorganic Zinc Rich Primer / Acrylic / Acrylic Paint System shall be used for shop and field painting of new structural steel except where otherwise noted. The color of the final finish coat for all interior steel surfaces shall be gray, Munsell No. 5B 7/1. The color of the final finish coat for the exterior and bottom flange of the fascia beams shall be Blue, Munsell No. 10B 3/6.
- 9. The embankment configuration shown shall be the minimum that must be placed and compacted prior to construction of the abutments.
- 10. Slipforming of parapets is not allowed.
- 11. Remove existing abutments and wingwalls to 5' below proposed ground. Remove existing piers to 2' below proposed ground. No temporary retention system is included in the plans for removal below grade of the existing creosoted timber piles under the approach slabs. These piles may be extracted or cut off by use of localized excavations. The piles adjacent to the stage construction line will require extraction. Cost included with the cost of Removal of Existing Structures No. 4 and No. 5. If pile deterioration is such that extraction becomes infeasible by determination of the Engineer, then localized earth retention with excavation and pile cutoff will be paid for according to Article 109.04 of the Standard Specifications.
- 12. Areas of the existing bridge have permanent protective shield in place. If any part of the existing permanent protective shield system is to be re-used as temporary protective shield. the Contractor shall submit design calculations to the Engineer proving the system meets the requirements of Article 501.03 of the Standard Specifications. The calculations shall be prepared and sealed by an Illinois Licensed Structural Engineer.

INDEX OF SHEETS

| SUI | General Plan and Elevation |
|--|---|
| SC2 | General Data 1 of 2 |
| SC3 | General Data 2 of 2 |
| 504 | Footing Lavout |
| 505 | Stage Construction Details 1 of 2 |
| 505 | Stage Construction Details 1 of 2 |
| 200 | Stage Construction Deraits 2 of 2 |
| SC7 | Temporary Sheeting Details |
| SC8 | Temporary Barrier Details |
| SC9 | Top of Deck Elevation Layout |
| SCO | Top of Deck Elevations 1 of 6 |
| SC11 | Top of Deck Flevations 2 of 6 |
| SC12 | Top of Deck Elevations 3 of 6 |
| SC13 | Top of Deck Elevations 4 of 6 |
| 5015 | Top of Deek Elevations F of C |
| SC14 CC15 | Top of Deck Elevations 5 of 6 |
| 5015 | TOP OF Deck Elevations 6 of 6 |
| SC16 | lop of West Approach Slab Elevations |
| SC17 | Top of East Approach Slab Elevations |
| SC18 | Superstructure 1 of 3 |
| SC19 | Superstructure 2 of 3 |
| SC20 | Superstructure 3 of 3 |
| SC21 | Superstructure Details 1 of 2 |
| 5022 | Superstructure Details 2 of 2 |
| 5022 | Diaphraam Dotaile 1 of 2 |
| 5025 | Diaphilagiii Deraiis I or 2 |
| SUZ4 | Diaphragm Derails 2 of 2 |
| SC25 | Bridge Approach Slab Defails I of 3 |
| SC26 | Bridge Approach Slab Defails 2 of 3 |
| SC27 | Bridge Approach Slab Details 3 of 3 |
| SC28 | Framing Plan 1 of 2 |
| SC29 | Framing Plan 2 of 2 |
| SC30 | Girder Details 1 of 4 |
| SC 31 | Girder Details 2 of 4 |
| 5032 | Girder Details 3 of 4 |
| 5032 | Cirder Details 4 of 4 |
| 2024 | UND Non Cuided Expension Destring Details |
| 5634 | HLMR Non-Guidea Expansion Bearing Details |
| 5035 | west Abutment Details 1 of 3 |
| C.U. XU. | |
| 3636 | west Adutment Details 2 of 5 |
| SC37 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 |
| SC37 SC38 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 |
| SC37 SC38 SC39 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 |
| SC37 SC37 SC38 SC39 SC40 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 |
| SC38 SC38 SC39 SC40 SC41 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 |
| SC38 SC38 SC39 SC40 SC41 SC42 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC42 SC43 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Solicer Assembly Details |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC42 SC43 SC44 SC44 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Perior Loss 1 of 5 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC42 SC43 SC44 SC45 SC44 | West Aburment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC46 SC46 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC46 SC46 SC47 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC43 SC44 SC45 SC46 SC47 SC48 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC49 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC49 SC50 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC42 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC46 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 SC53 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 SC52 SC54 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC47 SC48 SC50 SC51 SC52 SC53 SC55 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC46 SC47 SC48 SC45 SC50 SC51 SC52 SC51 SC52 SC53 SC54 SC55 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC42 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 SC53 SC54 SC55 SC55 SC55 SC56 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 SC54 SC55 SC55 SC55 SC56 SC57 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC49 SC50 SC51 SC52 SC53 SC54 SC55 SC55 SC55 SC55 SC56 SC57 SC58 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC50 SC51 SC52 SC51 SC52 SC53 SC54 SC55 SC56 SC57 SC58 SC59 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 SC53 SC54 SC55 SC56 SC57 SC58 SC59 SC60 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC45 SC46 SC47 SC48 SC59 SC51 SC55 SC55 SC56 SC57 SC58 SC59 SC60 SC61 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 1 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC49 SC50 SC51 SC52 SC53 SC54 SC55 SC55 SC55 SC55 SC55 SC55 SC56 SC57 SC58 SC59 SC60 SC61 SC62 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 3 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |
| SC36 SC37 SC38 SC39 SC40 SC41 SC42 SC43 SC44 SC45 SC44 SC45 SC46 SC47 SC48 SC50 SC51 SC52 SC53 SC55 SC55 SC55 SC55 SC55 SC55 SC55 | West Abutment Details 2 of 3 West Abutment Details 3 of 3 East Abutment Details 2 of 3 East Abutment Details 2 of 3 East Abutment Details 3 of 3 Pier Details 1 of 2 Pier Details 2 of 2 HP Pile Details Bar Splicer Assembly Details Soil Boring Logs 1 of 5 Soil Boring Logs 2 of 5 Soil Boring Logs 4 of 5 Soil Boring Logs 5 of 5 Existing Plans Existing Plans |

| ITEM | UNIT | SUPER | SUB | TOTAL |
|---|---------|---------|----------------|---------|
| Removal of Existing Structures No. 4 | Each | | | 1 |
| Removal of Existing Structures No. 5 | Each | | | 1 |
| Protective Shield | Sq. Yd. | 512 | | 512 |
| Structure Excavation | Cu. Yd. | | 1,419 | 1,419 |
| Concrete Structures | Cu. Yd. | | 671 . 4 | 671.4 |
| Concrete Superstructure | Cu. Yd. | 1,700.3 | | 1,700.3 |
| Bridge Deck Grooving | Sq. Yd. | 4,722 | | 4,722 |
| Protective Coat | Sq. Yd. | 5,552 | | 5,552 |
| Furnishing and Erecting Structural Steel | L Sum | 0.60 | | 0.60 |
| Stud Shear Connectors | Each | 12,348 | | 12,348 |
| Reinforcement Bars, Epoxy Coated | Pound | 356,810 | 104,690 | 461,500 |
| Bar Splicers | Each | 2,698 | 320 | 3,018 |
| Mechanical Splicers | Each | 16 | 120 | 136 |
| Slope Wall 4 Inch | Sq. Yd. | | 1,319 | 1,319 |
| Furnishing Steel Piles HP12X53 | Foot | | 4,118 | 4,118 |
| Furnishing Steel Piles HP14X89 | Foot | | 4,312 | 4,312 |
| Driving Piles | Foot | | 8,430 | 8,430 |
| Test Pile Steel HP12X53 | Each | | 2 | 2 |
| Test Pile Steel HP14X89 | Each | | 1 | 1 |
| Pile Shoes | Each | | 138 | 138 |
| Name Plates | Each | 1 | | 1 |
| Anchor Bolts, 1" | Each | 56 | | 56 |
| Anchor Bolts, 1 ¹ 2" | Each | 36 | | 36 |
| Geocomposite Wall Drain | Sq. Yd. | | 348 | 348 |
| Temporary Sheet Piling | Sq. Ft. | | 2,253 | 2,253 |
| Pipe Underdrains for Structures 4" | Foot | | 343 | 343 |
| High Load Multi-Rotational Bearings, Non-Guided Expansion, 600K | Each | 4 | | 4 |
| Granular Backfill for Structures | Cu. Yd. | | 826 | 826 |
| | | | | |



Job No. 10056 312 565 0450

| FILE NAME = | USER NAME = mbecker | DESIGNED - | MFB | REVISED - | | GENERAL DATA 1 OF 2 | | SECTION | | COUNTY | TOTAL SP | EET |
|----------------------------|-----------------------|------------|---------|-----------|------------------------------|------------------------------|------|-------------------|------------------|---------|----------|-----|
| I [| | CHECKED - | MRB/SCW | REVISED - | STATE OF ILLINOIS | | 74 9 | 0-[14R:(14HB-4.14 | .14HVB)BR1 T | AZEWELL | 2433 1 | 978 |
| 0900169_68620_02_gndt1.dgn | PLOT SCALE = | DRAWN - | PRT | REVISED - | DEPARTMENT OF TRANSPORTATION | STRUCTURE NU. 090-0169 | | | С | ONTRACT | NO. 68F | 20 |
| í E | PLOT DATE = 8/20/2012 | CHECKED - | MRB | REVISED - | | SHEET NO. SC2 OF SC63 SHEETS | | ILLIN | NOIS FED. AID PR | OJECT | | |