STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Schedule of Overhead Sign Structure Replacement

Location	Location No.: 7-01 State I.D. No.: 7S015I057L189.9							
County:	Coles	Route:	I - 57	M.P.:	189.9	Direc	tion: SB	
Description	Unit	Quantity						
REMOVE		EACH	1.00					
OVERHEA	AD SIGN STRUCTUR	RE - SPAN	, TYPE I A			FOOT	96.00	
DRILLED	SHAFT CONCRETE	FOUNDAT	TION			CU YD	20.50	
REMOVE	CONCRETE FOUND	O NOITA	VERHEAD			EACH	2.00	
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE							2.00	
REMOVE & REINSTALL SIGN PANEL							270.50	
REMOVE & REINSTALL WALKWAY							51.00	
FURNISH & INSTALL SAFETY CHAIN							2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION							12.00	
DISCONNECT / RECONNECT ELECTRIC SERVICE							1.00	
RELOCATE ELECTRIC SERVICE							1.00	
This struc	This structure is being completely replaced.							

Location No.: 7-02	State I.D.	No.:	7 S	7R161.3			
County: Effingham	Route:	1 - 57	M.P.:	161.3	Direc	ion: NB	
Description of Work	Unit	Quantity					
REMOVE & RE-ERECTOVER	HEAD SIGN	STRUCT	URE - SPA	AN	EACH	1.00	
STRUCTURAL STEEL SUPPORT	OVERHEAD	SIGN ST	RUCTURE		EACH	2.00	
FURNISH & INSTALL SADDLI	E SHIM BLO	CK			EACH	4.00	
FURNISH & INSTALL INTERN	IAL TRUSS [DAMPER			EACH	1.00	
OVERHEAD SIGN STRUCTURE WALKWAY						89.00	
REPLACE / TIGHTEN CLIP PI	REPLACE / TIGHTEN CLIP PER SIGN						
REPAIR HANDRAIL LOCKING PIN CONNECTION						[12.00	
FURNISH & INSTALL SAFETY CHAIN						2.00	
DISCONNECT / RECONNECT ELECTRIC SERVICE						1.00	
Work to be completed between 11:00pm and						am	
Replace Existing End Supports.							
Existing plans show end suppo	rts as 10-inc	h column	s.				

Location No.:	7-03	State I.D	No.:	7S025I057R162.9					
County:	Effingham	Route:	1 - 57	M.P.:)	Direct		NB	
Description of Work								Qua	ntity
REMOVE & RE	REMOVE & RE-ERECTOVERHEAD SIGN STRUCTURE - SPAN								.00
STRUCTURAL S	TEEL SUPPORT	OVERHEAD	SIGN ST	RUCTURE		E/	CH	2.00	
FURNISH & IN	STALL SADDLE	SHIM BLC	CK			EACH		4.	.00
FURNISH & IN	FURNISH & INSTALL INTERNAL TRUSS DAMPER							1.	.00
OVERHEAD SIGN STRUCTURE WALKWAY							TO	88	.00
REPLACE / TIGHTEN CLIP PER SIGN							\CH	1.	00
REPAIR HANDRAIL LOCKING PIN CONNECTION							/CH	8	00
FURNISH & INSTALL SAFETY CHAIN							\CH	2.	00
DISCONNECT / RECONNECT ELECTRIC SERVICE							\CH	1.	00
Work to b	e completec	1 betw	veen 11	:000	n au	nd	7:0	10 a	m
Replace Existing End Supports.									
Existing plans s	show end suppor	ts as 10-in	ch column	s.					

Location No.: 7-04 State I.D. No.: 7S025I0						70L099.0		
County: Ef	fingham	Route:	1 - 70	M.P.:	99	Direc	tion: WB	
Description of Work							Quantity	
REMOVE & RE-	ERECTOVERH	EAD SIGN	STRUCT	JRE - SPA	N	EACH	1.00	
STRUCTURAL ST	EEL SUPPORT	OVERHEAD	SIGN STF	UCTURE		EACH	2.00	
FURNISH & INST	TALL SADDLE	SHIM BLO	CK			EACH	4.00	
FURNISH & INST	FURNISH & INSTALL INTERNAL TRUSS DAMPER						1.00	
OVERHEAD SIGN STRUCTURE WALKWAY						FOOT	89.00	
REPLACE / TIGHTEN CLIP PER SIGN						EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION						EACH	3.00	
DISCONNECT / RECONNECT ELECTRIC SERVICE						EACH	1.00	
FURNISH & INSTALL SAFETY CHAIN						EACH	2.00	
Pontosa Eviatin	a End Cuppe	+0					<u> </u>	
Replace Existin			1	· · · · · · · · · · · · · · · · · · ·				
Existing plans sh	ow ena suppor	ts as 10-inc	n column	3.			<u> </u>	

Location No.:	7-05	State I.D). No.:	79	3025105	7L164.3		
County:	County: Effingham Route: I - 57 M.P.: 164.							
Description of	Unit	Quantity						
REMOVE & RE	REMOVE & RE-ERECTOVERHEAD SIGN STRUCTURE - SPAN							
STRUCTURAL S	TEEL SUPPORT	OVERHEA	D SIGN ST	RUCTURE		EACH	2.00	
FURNISH & IN	STALL SADDLE	SHIM BL	OCK			EACH	4.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER							1.00	
OVERHEAD SI	GN STRUCTUR	E WALKV	VAY			FOOT	89.00	
TIGHTEN U-BO	TIGHTEN U-BOLT							
REPAIR HANDRAIL LOCKING PIN CONNECTION							8.00	
FURNISH & INSTALL SAFETY CHAIN							2.00	
DISCONNECT / RECONNECT ELECTRIC SERVICE							1.00	
	·							
Replace Exist	ing End Suppoi	ts.						
Existing plans s	show end suppor	ts as 10-ir	ich column	s.				

Location No.: 7-06	State I.D. No.:	3025105	57L163.8				
County: Effingham	Route: 1 - 57	oute: I - 57 M.P.: 163.8					
Description of Work	Unit	Quantity					
REMOVE & RE-ERECTOVERH	HEAD SIGN STRUCT	URE - SF	PAN .	EACH	1.00		
STRUCTURAL STEEL SUPPORT	OVERHEAD SIGN ST	RUCTURE		EACH	2.00		
FURNISH & INSTALL SADDLE	SHIM BLOCK			EACH	4.00		
FURNISH & INSTALL INTERNA	AL TRUSS DAMPER			EACH	1.00		
OVERHEAD SIGN STRUCTUR		FOOT	103.00				
REPAIR HANDRAIL LOCKING	EACH	12.00					
DISCONNECT / RECONNECT		EACH	1.00				
Replace Existing End Suppo							
Existing plans show end support	ts as 10-inch columr	s.					