



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION








SECTION A-A (5 Required)



(Looking North)



TYPICAL SECTION AT ABUTMENTS

(Horizontal dimensions at right L's)

- ** Existing dowel rods are to be burned off, ground flush, and sealed with epoxy prior to placement of new beams. Cost included in Removal of Existing PPC Deck Beams.

 After beams have been erected holes shall be drilled into cap and dowel rods placed. Dowel holes shall be filled with non-shrink grout to top of beam and allowed to cure a minimum of 24 hours prior to grouting the shear keys.
- *** Joint shall be filled with non-shrink grout. Dimension may vary to accommodate tolerance in beam lengths.

REPAIR DETAILS SN 092-0176

	SHEET NO. 4 5 SHEETS	F.A.S. RTE.	S. SECTION			COUNTY	TOTAL SHEETS	SHEET NO.		
		331	(79-102)2009BBR			VERMILION	16	12		
						CONTRACT	NO. 70	749		
		FED. ROAD DIST. NO.		ILLINOIS	INOIS FED. AID PROJECT					

AJBDESIGNED EXAMINED GGHCHECKED PASSED Steffen AJBGGHCHECKED

5 of 5 for additional details.