



* Due to the size and location of patch #8 it will need to be broken into 3 sections. This will prevent exposing all of the top reinforcement in that area.

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		DECK SLAB REPAIR (FD TY 1)	DECK SLAB REPAIR (FD TY 2)
		SO	YD		
1	2.0' X 4.5'				1.0
2	2.0' X 4.5'				1.0
3	2.0' X 4.5'				1.0
4	2.0' X 4.5'				1.0
5	12.0' X 18.0'	24.0			
6	2.0' X 2.0'	0.4			
7	5.0' X 5.0'	2.8			
* 8	4.0' X 27.0'	12.0			
9	4.0' X 7.0'	3.1			
10	4.0' X 17.0'	7.6			

THE SIZES SHOWN GRAPHICALLY ABOVE ARE APPROXIMATE. SEE THIS TABLE FOR ACTUAL SIZES.

PATCHING LEGEND

PARTIAL DEPTH

FULL DEPTH

DATE OF SURVEY: MAY 2008
 SURVEY BY:
 M. ALLEN & K. THOELE
 METHOD OF SURVEY: VISUAL

BRIDGE DECK PATCHING
 LAWRENCE COUNTY
 FAP-327WB (US-50)
 FEATURE CROSSED FAS 1827
 LAWRENCEVILLE- VINCENNES
 AIRPORT ROAD
 SN 051-0016

SHEET NO. 7
 15 SHEETS

016