



CONTROL POINT COORDINATES

Traverse Point	Coordinates
P.I. # 3	N=1761591.97 E=1046554.64
P.I. # 7	N=1761260.48 E=1046607.96
P.I. #16	N=1760803.65 E=1045798.88
P.I. # 21	N=1762236.39 E=1046612.15
P.I. # 22	N=1761881.44 E=1046706.43

Designed By RLP Checked By JJF
 Drawn By RLP Checked By JJF
 11/22/2005 09:15:40 AM H:\0wr\Proj\Imp\Projects\Rockdale\PlanSheets\TRAVERSEREFERENCEMARKS.dgn