


JOINT REPAIR DETAILS S.N. 092-0001 (EB) & 092-0002 (WB)

(EXPANSION JOINTS OVER PIERS)



SECTION AT EXISTING JOINT





<u>NOTES</u>

THE EXISTING PREFORMED JOINT SEALS SHALL BE REMOVED AND THE STEEL JOINT ARMOR SHALL BE CLEANED PRIOR TO THE INTALLATION OF THE PROPOSED SILICONE JOINT SEALER. COST INCLUDED WITH SILICONE JOINT SEALER, 1.5"

BILL OF MATERIALS - TWO STRUCTURES

ITEM	UNIT	TOTAL
SILICONE JOINT SEALER, 1.5"	FOOT	149.0

FILE NAME =	USER NAME = simsgm	DESIGNED - GMS	REVISED -			JOINT REPAIR	DETAIL C		F.A.I.	SECTION	١	COUNTY	TOTAL SHEET
c:\pw_work\pwidot\simsgm\dØ187665\	d590963 Bridge Repairs.dgn	DRAWN - GMS	REVISED -	STATE OF ILLINOIS	S.N. 092-0001 (EB) & 092-0002 (WB)			74 (92-9BR)I-1		-1	VERMILION	15 12	
	PLOT SCALE = 40.0001 ' / IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION							CONTRACT	NO. 90963	
1	PLOT DATE = 10/18/2010	DATE -	REVISED -		SCALE:	SHEET NO OF - SHEETS	STA.	TO STA.	FED. ROAD DI	ST. NO. ILLI	INOIS FED. AID	PROJECT	