


CSS - MISSOURI TAIL SPAN - SPAN 9

REPAIRS LIST - SPAN 9

I.D.	Description	Pay Item	Units	Quantity
040	Concrete Spall	Deck Slab Repair (Partial)	SQ. YD.	0.11
041	Clogged Scupper	Cleaning Bridge Scuppers and Downspouts	Each	1
042	Clogged Scupper	Cleaning Bridge Scuppers and Downspouts	Each	1
043	Clogged Scupper	Cleaning Bridge Scuppers and Downspouts	Each	1
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-



DECK SLAB REPAIR (PARTIAL)

DESIGNED -	EXAMINED _____ DATE - _____
CHECKED -	ENGINEER OF STRUCTURAL SERVICES
DRAWN Rod	PASSED _____
CHECKED MNM	ENGINEER OF BRIDGES AND STRUCTURES

**STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION**

**REPAIRS TO - CSS - DECK SLAB and PARAPETS - SPAN 9
 STRUCTURE NO. 060-0255**

SHEET NO. 07 OF 48 SHEETS

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
304	100B-DS-1	MADISON	58	17
CONTRACT NO. 76E73				

ILLINOIS FED. AID PROJECT