



MISSOURI BRIDGE APPROACH SLAB



REPAIRS LIST - MISSOURI APPROACH SLAB

I.D.	Description	Pay Item	Units	Quantity
122	Spalled Concrete Curb	Structural Repair of Concrete (Depth equal to or less than 5 Inches)	SQ. FT.	3.0
139	1/8" Slab Crack West Bound Lanes	Epoxy Crack Injection	FOOT	25
140	1/8" Slab Crack West Bound Lanes	Epoxy Crack Injection	FOOT	25
141	3/8" Slab Crack West Bound Lanes	Epoxy Crack Injection	FOOT	30

DESIGNED -	EXAMINED _____	DATE - _____
CHECKED -	ENGINEER OF STRUCTURAL SERVICES	
DRAWN Rod	PASSED _____	
CHECKED MNM	ENGINEER OF BRIDGES AND STRUCTURES	

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**REPAIRS TO - MISSOURI APPROACH SLAB
STRUCTURE NO. 060-0255**

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
304	100B-1D5-1	MADISON	58	57
CONTRACT NO. 76E73				
ILLINOIS FED. AID PROJECT				