

STATE OF ILLINOIS  
DEPARTMENT OF TRANSPORTATION

Various Routes  
OVD SIN STR REP & REPL 2006-9  
Various Counties  
Sheet 48 of 114  
Contract Number 44904

District 4  
Schedule of Locations for Truss Repair & Replacement

Location No.: 4-01		State I.D. No.: 4S0901474R012.7	
County:	Route:	M.P.:	Direction:
Tazewell	I-474	12.7	EB
Description of Work	Unit	Quantity	
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00	
REMOVE CONCRETE FOUNDATION OVERHEAD	EACH	2.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	10.00	
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00	
PAINT OVERHEAD SIGN SUPPORT	EACH	2.00	
REPLACE / TIGHTEN CLIP PER SIGN	EACH	1.00	
FURNISH & INSTALL WALKWAY TIE DOWN BOLT	EACH	1.00	
DRILLED SHAFT CONCRETE FOUNDATION	CU YD	21.50	
RELOCATE ELECTRIC SERVICE	EACH	1.00	
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	68.00	
REMOVE & RE-ERECT OVERHEAD SIGN END SUPPORT	EACH	2.00	
DISCONNECT/RECONNECT ELECTRIC SERVICE	EACH	1.00	

Location No.: 4-05		State I.D. No.: 4S0901474R012.2	
County:	Route:	M.P.:	Direction:
Tazewell	I-474	12.2	EB
Description of Work	Unit	Quantity	
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	4.00	
REPAIR CONCRETE FOUNDATION FOR OVERHEAD SIGN STRUCTURE	EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	9.00	
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00	
FURNISH & INSTALL INTERNAL TRUSS CLAMP	EACH	1.00	
PAINT OVERHEAD SIGN SUPPORT	EACH	2.00	
REPLACE U-BOLT	EACH	12.00	

Location No.: 4-02		State I.D. No.: 4C0721474L003.41	
County:	Route:	M.P.:	Direction:
Peoria	I-474	3.41	WB
Description of Work	Unit	Quantity	
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	1.00	
REPAIR CONCRETE FOUNDATION FOR OVERHEAD SIGN STRUCTURE	EACH	1.00	
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	4.00	
PAINT OVERHEAD SIGN SUPPORT	EACH	1.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00	

Location No.: 4-03		State I.D. No.: 4C090S116L005.9	
County:	Route:	M.P.:	Direction:
Tazewell	IL 116	5.9	WB
Description of Work	Unit	Quantity	
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	1.00	
TIGHTEN CANTILEVER CONNECTION	EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	5.00	
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00	

Location No.: 4-04		State I.D. No.: 4C072U024R022.76	
County:	Route:	M.P.:	Direction:
Peoria	US - 24	22.76	EB
Description of Work	Unit	Quantity	
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	1.00	
TIGHTEN CANTILEVER CONNECTION	EACH	2.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	5.00	
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00	
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00	