## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

## District 4 Schedule of Locations for Truss Repair & Replacement

Location	No.:	4-01	State I.D. No.: 40			C090U02	)				
County:		Tazewell	Route:	US	24	M.P.:	1 Direction: E				
Description of Work								Unit	Quantity		
REMOVE OVERHEAD SIGN STRUCTURE-CANTILEVER								EACH	1.00		
OVERHEAD SIGN STRUCTURE CANTILEVER 2CA3-0X5-6								FOOT	29.00		
DRILLED SHAFT CONCRETE FOUNDATION								CU YD	6.40		
REMOVE CONCRETE FOUNDATION-OVERHEAD								EACH	1.00		
REMOVE & REINSTALL SIGN PANEL								SQ FT	140.00		
REMOVE & REINSTALL WALKWAY								FOOT	20.00		
RELOCATE ELECTRIC SERVICE							EACH	1.00			
REPAIR HANDRAIL LOCKING PIN CONNECTION								EACH	4.00		
FURNISH & INSTALL SAFETY CHAIN								EACH	2.00		

Location	No.: 4-04	State I	.D. No.:	4	C102I074	L114.8		
County:	Woodford	Route:	I-74	M.P.:	M.P.: 114.8 Direction: W			
Descripti		Unit	Quantity					
REMOVE		EACH	1.00					
OVERHE	5'-6")	FOOT	30.00					
DRILLED		CU YD	8.70					
REMOVE		EACH	1.00					
REMOVE		SQ FT	78.00					
REMOVE		FOOT	20.00					
REPAIR H		EACH	4.00					
FURNISH		EACH	2.00					
There is r	o sign lighting on this stru	icture.						

Location	No.:	4-02	State I.D	. No.:	06R009.2			
County:		Peoria	Route:	IL 6	M.P.:	9.2	Direc	tion: EB
Description of Work								Quantity
REMOVE	EACH	1.00						
OVERHEAD SIGN STRUCTURE CANTILEVER 2CA3-0X5-6								28.00
DRILLED SHAFT CONCRETE FOUNDATION								6.40
REMOVE CONCRETE FOUNDATION-OVERHEAD								1.00
REMOVE & REINSTALL SIGN PANEL								159.50
REMOVE	FOOT	16.00						
RELOCATE ELECTRIC SERVICE								1.00
REPAIR HANDRAIL LOCKING PIN CONNECTION								4.00
FURNISH & INSTALL SAFETY CHAIN								2.00

Location	No.: 4-03	State I.D. No.: 4C090U02				24L000.9			
County:	Tazewell	Route: US 24 M.P.: 0.9				Direction: WB			
Descripti	Unit	Quantity							
REMOVE OVERHEAD SIGN STRUCTURE-CANTILEVER								1.00	
OVERHE	OVERHEAD SIGN STRUCTURE CANTILEVER 2CA3-0X5-6								
DRILLED SHAFT CONCRETE FOUNDATION								8.70	
REMOVE CONCRETE FOUNDATION OVERHEAD								1.00	
REMOVE & REINSTALL SIGN PANEL								232.50	
REMOVE	FOOT	22.00							
RELOCATE ELECTRIC SERVICE								1.00	
REPAIR HANDRAIL LOCKING PIN CONNECTION								4.00	
FURNISH & INSTALL SAFETY CHAIN								2.00	
REPLAC	REPLACE / TIGHTEN CLIP PER SIGN								