


CONCRETE OVERLAY AT FLOOR DRAINS TO REMAIN

* € 34" Ø H.S. Bolt with

2 washers & locknut


15₁₆ " ∅ holes in web. See Notes.

B₹



3'-0"

PLAN



SECTION A-A

^{-l}g" x 4" x 6" Fabric Pad*


,--- Mid height of Girder web

*Cost included with

Floor Drain Extension.


SECTION B-B

,		
DESIGNED	-	JLS
CHECKED	-	KWS
DRAWN	-	RMG
CHECKED	_	KWS
CHECKED		- KWO



** Contractor shall increase scarification thickness or reduce overlay thickness as directed by the

(6 total)



SCARIFICATION & OVERLAY DETAIL AT PARAPET

difred benesch & company
Engineers · Surveyors · Planners
205 North Michigan Avenue, Suite 2400
Chicago, Illinois 60001
312-565-0450 Job No. 10032.13

BILL OF MATERIAL

SYMB0L	ITEM	UNIT	QUANTITY
	Deck Slab Repair (Partial)	Sq. Yd.	16.9▲
	Deck Slab Repair (Full Depth, Type I)	Sq. Yd.	5.0
	Deck Slab Repair (Full Depth, Type II)	Sq. Yd.	9.3
	Cleaning and Painting Exposed Rebar (Special)	Sq. Ft.	50
	Protective Shield	Sq. Yd.	2,933
	Bridge Deck Grooving	Sq. Yd.	2,384
Bridge De	Protective Coat	Sq. Yd.	2,986
	Bridge Deck Microsilica Concrete Overlay, 2 ¹ 4"	Sq. Yd.	2,466
	Bridge Deck Hydro- Scarification, ¹ 2"	Sq. Yd.	2,466
Floor Drain Extension		Each	. 6

For information only to assist the Contractor in bidding. See Special Provision for "Bridge Deck Microsilica Concrete Overlay."

Notes:

- 1. Deck repair areas are estimated based on an IDOT inspection in October of 2009. Actual repair areas and locations shall be determined by the Engineer and shown on As-Built plans.
- 2. Protective Shield required for scarification operations and deck slab and/or parapet repairs shall be installed according to Article 501.03 of the Standard Specifications. For limits of Protective Shield, see General Plan and Elevation sheet.
- 3. Extreme care shall be taken not to damage existing underpass lighting during construction. See Special Provision for "Protection and Maintenance of Existing Underpass Lighting".
- 4. Deck drains (downspouts, floor drains, and scuppers) shall be cleaned prior to placement of the Microsilica Concrete Overlay. Cost of cleaning the deck drains is included in Bridge Deck Hydro-Scarification, 12".
- 5. Proposed bolt holes in the existing Girder shall be subpunched or subdrilled ¹³16" diameter and reamed in the field to ¹⁵16" diameter. Cost included with Floor Drain Extension.

BRIDGE DECK REPAIRS STRUCTURE NO. 022-0106

SECTION COUNTY SHEET NO. 3 290 2009-1151 DUPAGE 27 19 SHEETS

TOTAL SHEET NO. 8 CONTRACT NO. 60J34 FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT