
BILL OF MATERIAL

SYMBOL	ITEM	UNIT	QUANTITY
	Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)	Sq. Ft.	191
	Concrete Sealer	Sq. Ft.	797

PIER 3 REPAIRS - EAST FACE

(Looking West)



(Looking East)

WEST ABUTMENT

**Extreme care shall be taken not to damage existing junction box or conduits.

See Special Provision for "Protection and Maintenance of Existing Underpass Lighting".

EAST ABUTMENT

PIER 3 REPAIRS - WEST FACE

Note:

Substructure repair areas are estimated based on IDOT field notes from October of 2009. Actual repair areas and locations shall be determined by the Engineer and shown on the As-Built plans.

DESIGNED CHECKED KWS DRAWN

KWS

CHECKED

alfred benesch & company
Engineers · Surveyors · Planners
205 North Michigan Avenue, Suite 2400
Chicago, Lilinois 60801
312-565-0450 Job No. 10032.13

SHE	ΞT	NO.	11			
19	9 SHEETS					

STRUCTURE NO. 022-0106								
F.A.I. RTE.	SECTION			COUNTY	TOTAL SHEETS		SHEET NO.	9
290	2009-1151			DUPAGE	27		16	3
				CONTRACT	NO.	60	J34	1
FED. RC	D. ROAD DIST. NO. ILLINOIS FED. AID PROJECT						Ì	

SUBSTRUCTURE REPAIRS

^{*}Substructure repairs to be completed simultaneously with bearing replacement at Pier 3.

Cost for Temporary Shoring is included with Jack and Remove Existing Bearings.

See General Notes sheet for Pier 3 reaction table.