


TYPICAL BUTT JOINT AND BITUMINOUS TAPER

FOR MILLING AND RESURFACING



CHECKED BY BD400-05 (VI=BD32) REVISION DATE: 04/06/01

DRAWN BY