

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES:

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES.

 NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS) UNLESS OTHERWISE SHOWN

E NAME = USER N	NAME = leysa	DESIGNED		REVISED	-	J.A.F. 04-03
distatd\22x34\tc18.dgn		DRAWN	-	REVISED	~	J.A.F. 02-06
PLOT S	SCALE = 50.000 '/ IN.	CHECKED	-	REVISED	-	S.P.B. 01-07
PLOT D	DATE = 1/26/2010	DATE	-	REVISED	-	S.P.B. 12-09

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SIGNING FOR FLAGGING OPERATIONS			F.A. SECTION			COUNTY	TOTAL SHEETS	SHEET NO.		
AT WORK ZONE OPENINGS								781	655	
AI WORK LUNE UPENINGS					TC-18		CONTRACT NO.			
SCALE: NONE	SHEET NO. 1 OF 1 SHEETS	STA.	TO STA.	FED. R	DAD DIST. NO. 1	LLINOIS FED. AID PROJECT				