




INSTALLATION INSTRUCTIONS TO SUPPLEMENT THE MANUFACTURER'S INSTRUCTIONS

- 1. CLEAN THE CABLE THOROUGHLY 9" MIN. FROM THE END.
- 2. REMOVE INSULATION PER MANUFACTURER'S INSTRUCTIONS. DO NOT NICK THE CONDUCTOR. DO NOT PENCIL INSULATION ON L-824 TYPE C CABLE.
- 3. INSTALL PIN AND/OR RECEPTICAL WITH CRIMPING TOOL WHICH MUST BE COMPLETELY CLOSED BEFORE THE TOOL MAY BE REMOVED.
- 4. BE SURE CABLE AND CONDUCTOR FITTINGS ARE CLEAN. COAT THE CABLE INSULATION WITH INSULATION JELLY FROM THE CONNECTOR.
- 5. CAREFULLY INSERT CABLE INTO CONNECTOR TO THE PROPER DEPTH.
- 6. SLIP 14 INCH LENGTH OF HEAT SHRINK TUBING ON TRANSFORMER LEAD RAYCHEM TCS-13-14-U OR APPROVED EQUAL.
- 7. COMPLETE CONNECTION BY MATING THE PLUG AND RECEPTICAL. **CAUTION** BE SURE THE CABLE DOES NOT SLIP WHEN THE CONNECTION IS MADE.
- 8. APPLY RUBBER TAPE AND PLASTIC TAPE, ONE HALF LAPPED 1-1/2" ON EACH SIDE OF JOINT.
- 9. ANY CONNECTOR WHICH IS CONTAMINATED BY DIRT OR OTHER DELETERIOUS MATERIAL SHALL BE REMOVED NOT REINSTALLED.
- 10. CLEAN CONNECTOR AND CABLE INSULATION WITH WAX OR GREASE SOLVENT TO REMOVE SURFACE SILICONE, JELLY
- 11. WRAP SEALANT SECURELY AROUND THE CABLE. INSULATION TO EXTEND 1-1/2" BEYOND BOTH ENDS OF CONNECTORS. SEALANT SHALL BE RAYCHEM S-1052 (STRIPS) OR APPROVED EQUAL.
- 12. CENTER HEAT SHRINK OVER THE CONNECTOR. APPLY HEAT EVENLY BEGINNING AT THE CENTER AND WORKING AROUND CABLE TO ENDS. THERMOCHROMIC PAINT SHALL SHOW PROPER HEAT HAS BEEN USED. *** DO NOT OVER HEAT ***.
- 13. THE HEAT SOURCE SHALL BE AN ELECTRIC HEAT GUN OR A PROPANE WITH FLAME




FOR SPLICES IN HOMERUNS AND FOR EXTENSIONS TO EXISTING CABLES ONLY





TYPE C
FOR SPLICES AT RUNWAY LIGHTS,
TAXIWAY LIGHT AND SIGNS



TYPE D FOR SPLICES AT RUNWAY LIGHTS, TAXIWAY LIGHT AND SIGNS

NOTES:

- MATCH THE OUTSIDE DIAMETER OF CABLE INSIDE DIAMETER OF CONNECTOR SHALL PROPERLY
- WRAP WITH AT LEAST ONE LAYER OF RUBBER OR TAPE, ONE-HALF LAPPED, EXTENDING AT LEAST 1-1/2 INCHES ON EACH SIDE OF JOINT.

