

| | | | | |
|--------------|----------------|---------------|---------------------|---------------------|
| ROUTE | SECTION | COUNTY | TOTAL SHEETS | SHEET NUMBER |
| VARIOUS | 2012-042-I | COOK | 20 | 13 |

CONTRACT: 60V31

| LOCATION | COMB. CONC. C & G R&R (LF) | HMA SURF R&R VARIABLE DEPTH (SQYD) | SALT TOLERANT SODDING (SQYD) | SIDEWALK 5" R&R (SQFT) 18" CARRIAGE/ COURTESY | SIDEWALK 5" R&R (SQFT) 6' PARALLEL | SIDEWALK 8" R&R (SQFT) 6' PARALLEL | DRIVEWAY 8" R&R (SQFT) | DETECTABLE WARNINGS (ADA RAMPS) (SQFT) | REMARKS |
|--|----------------------------|------------------------------------|------------------------------|---|------------------------------------|------------------------------------|------------------------|--|--|
| 6039 South Mayfield Avenue | | 0.0 | 0.0 | 22.5 | 180.0 | 0.0 | | | Replace 6 Sidewalk Squares and Courtesy Walk |
| 6105 South Mayfield Avenue | | 0.0 | 0.0 | 22.5 | 180.0 | 0.0 | | | Replace 6 Sidewalk Squares and Courtesy Walk |
| 6110 South Mayfield Avenue | 3.0 | 0.5 | 0.4 | 9.0 | 0.0 | 0.0 | | | Replace 3 Feet of Curb, 3 Feet of Carriage Walk, and 1 Courtesy Walk Square |
| 6204 South Mayfield Avenue | | 0.0 | 0.0 | 22.5 | 180.0 | 0.0 | | | Replace 6 Sidewalk Squares and Courtesy Walk |
| 6228 South Mayfield Avenue | 10.0 | 1.7 | 1.4 | 15.0 | 0.0 | 0.0 | | | Replace Curb In Front of House and 10 Feet of Courtesy Walk |
| 6234 to 6238 South Mayfield Avenue | 7.0 | 1.2 | 0.9 | 3.0 | 0.0 | 0.0 | | | Replace 7 Feet of Broken Curb |
| 6105 South McVicker Avenue | 10.0 | 1.7 | 1.4 | 3.0 | 0.0 | 0.0 | | | Replace Curb In Front of House |
| 6235 South McVicker Avenue | 10.0 | 1.7 | 1.4 | 3.0 | 0.0 | 0.0 | | | Replace and Raise Curb |
| 6136 South Meade Avenue | | 0.0 | 0.0 | 22.5 | 180.0 | 0.0 | | | Replace 6 Sidewalk Squares, 2 Courtesy Walk Squares, and 3 Carriage Walk Squares |
| 5751 South Melvina Avenue | | 0.0 | 0.0 | 0.0 | 90.0 | 0.0 | | | Replace 3 Sidewalk Squares Broken from Tree |
| 6035 South Merrimac Avenue | 10.0 | 1.7 | 1.4 | 3.0 | 0.0 | 0.0 | | | Replace Damaged Curb |
| 7159 South Millard Avenue | | 0.0 | 0.0 | 13.5 | 900.0 | 120.0 | | | Replace 34 Front and Side Sidewalk Squares and 3 Side Courtesy Walk Squares |
| 7158 South Millard Avenue/7159 South Lawndale Avenue | 40.0 | 6.7 | 0.0 | 0.0 | 0.0 | 60.0 | 60.0 | 20.0 | Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron |
| 7200 South Millard Avenue/7201 South Lawndale Avenue | 40.0 | 6.7 | 3.4 | 0.0 | 0.0 | 60.0 | 30.0 | 20.0 | Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron |
| 6040 South Monitor Avenue | | 0.0 | 0.0 | 22.5 | 180.0 | 0.0 | | | Replace 6 Sidewalk Squares and Courtesy Walk |
| 6028 South Moody Avenue | 5.0 | 0.9 | 0.9 | 0.0 | 0.0 | 0.0 | | | Raise Curb and Sewer Catch Basin |
| 6241 South Moody Avenue | | 0.0 | 0.0 | 9.0 | 180.0 | 0.0 | | | Replace 6 Sidewalk Squares and 2 Courtesy Walk Squares |
| 6109 South Nashville Avenue | | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 25.0 | | Replace Concrete Behind House In Alley. Badly damaged and cracked from prior sewer cave-in |
| 6156 to 6158 South Nashville Avenue | | 0.0 | 0.0 | 0.0 | 60.0 | 0.0 | | | Replace Sidewalk That Is Collapsing and Is Causing a Serious Trip Hazard |
| 5830 South New England Avenue | | 0.0 | 0.0 | 22.5 | 240.0 | 0.0 | | | Replace 8 Sidewalk Squares and Entire Courtesy Walk |
| 6019 South Parkside Avenue | | 0.0 | 0.0 | 22.5 | 0.0 | 0.0 | | | Replace Service Walk/Courtesy Walk |
| 6028 South Parkside Avenue | | 0.0 | 0.0 | 22.5 | 0.0 | 0.0 | | | Replace Courtesy Walk |
| SUB-TOTAL | 135.0 | 22.8 | 11.2 | 238.5 | 2370.0 | 240.0 | 115.0 | 40.0 | |

ILLINOIS DEPARTMENT OF TRANSPORTATION
SCHEDULE OF QUANTITIES