

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2008-9
Various Counties
Sheet 26 of 105
Contract Number 44973

District 2
Schedule of Overhead Sign Structure Repair & Replacement

Location No.:	2-01	State I.D. No.:	2S101U020R023.8				
County:	Winnebago	Route:	US 20	M.P.:	23.8	Direction:	EB
Description of Work	Unit	Quantity					
REMOVE OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT FOR OVERHEAD SIGN STRUCTURE	EACH	2.00					
OVERHEAD SIGN STRUCTURE-SPAN, TYPE I-A (4' - 0" X 4' - 6")	FOOT	79.00					
REMOVE & REINSTALL WALKWAY	FOOT	34.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	2.00					
REMOVE & REINSTALL SIGN PANEL	SQ FT	391.50					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	4.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
RELOCATE ELECTRIC SERVICE	EACH	1.00					
DRILLED SHAFT CONCRETE FOUNDATIONS	CU YD	20.40					
REMOVE CONCRETE FOUNDATION - OVERHEAD	EACH	2.00					

Location No.:	2-02	State I.D. No.:	2S101U020L023.1				
County:	Winnebago	Route:	US 20	M.P.:	23.1	Direction:	WB
Description of Work	Unit	Quantity					
REMOVE OVERHEAD SIGN STRUCTURE - SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT FOR OVERHEAD SIGN STRUCTURE	EACH	2.00					
OVERHEAD SIGN STRUCTURE-SPAN, TYPE II-A (4' - 6" X 5' - 3")	FOOT	99.00					
REMOVE & REINSTALL WALKWAY	FOOT	46.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	2.00					
REMOVE & REINSTALL SIGN PANEL	SQ FT	438.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	10.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
RELOCATE ELECTRIC SERVICE	EACH	1.00					
DRILLED SHAFT CONCRETE FOUNDATIONS	CU YD	20.40					
REMOVE CONCRETE FOUNDATION - OVERHEAD	EACH	4.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
RELOCATE FLASHER CONTROLLER	EACH	1.00					

Location No.:	2-03	State I.D. No.:	2S101U020L022.6				
County:	Winnebago	Route:	US 20	M.P.:	22.6	Direction:	WB
Description of Work	Unit	Quantity					
REMOVE OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT FOR OVERHEAD SIGN STRUCTURE	EACH	2.00					
OVERHEAD SIGN STRUCTURE-SPAN, TYPE II-A (4' - 6" X 5' - 3")	FOOT	116.00					
REMOVE & REINSTALL WALKWAY	FOOT	64.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	2.00					
REMOVE & REINSTALL SIGN PANEL	SQ FT	381.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	10.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
RELOCATE ELECTRIC SERVICE	EACH	1.00					
DRILLED SHAFT CONCRETE FOUNDATIONS	CU YD	20.40					
REMOVE CONCRETE FOUNDATION - OVERHEAD	FOOT	2.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
REPLACE HANDRAIL SUPPORT	EACH	1.00					

Location No.:	2-04	State I.D. No.:	2C101HARRR024.7				
County:	Winnebago	Route:	Harr	M.P.:	24.7	Direction:	EB
Description of Work	Unit	Quantity					
REMOVE OVERHEAD SIGN STRUCTURE - CANTILEVER	EACH	1.00					
OVERHEAD SIGN STRUCTURE - CANTILEVER, TYPE II-C-A (36" X 5' - 6")	FOOT	30.00					
REMOVE & REINSTALL WALKWAY	FOOT	19.50					
REPLACE / TIGHTEN CLIPS PER SIGN	CU YD	1.00					
REMOVE & REINSTALL SIGN PANEL	SQ FT	252.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	2.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
RELOCATE ELECTRIC SERVICE	EACH	1.00					
DRILLED SHAFT CONCRETE FOUNDATIONS	FOOT	12.00					
REMOVE CONCRETE FOUNDATION - OVERHEAD	EACH	1.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					

Location No.:	2-05	State I.D. No.:	2S037I080R009.4				
County:	Henry	Route:	I - 80	M.P.:	9.4	Direction:	EB
Description of Work	Unit	Quantity					
REMOVE & RE-ERCT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
STRUCTURAL STEEL SUPPORT OVERHEAD SIGN STRUCTURE	EACH	2.00					
FURNISH & INSTALL SADDLE SHIM BLOCK	EACH	4.00					
REPLACE / TIGHTEN CLIPS PER SIGN	EACH	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	4.00					
REPLACE U-BOLT	EACH	2.00					
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	57.00					