



STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

| | | | | | |
|-----------------------|----------|-------------------|---------|-----------|-------------|
| ROUTE NO. | SECTION | COUNTY | STATION | SHEET NO. | SHEET NO. 5 |
| FAI 64 | 95-6VB-1 | WASHINGTON | 33 55 | 7 SHEETS | |
| FED. ROAD DIST. NO. 7 | ILLINOIS | FED. AID PROJECT- | | | |

Contract #76A39



WEST ABUTMENT - SN 095-0061 (EB)




WEST ABUTMENT - SN 095-0062 (WB)

BILL OF MATERIAL
(SN 095-0061)


| ITEM | UNIT | TOTAL |
|--|---------|-------|
| Structural Repair of Concrete (Depth equal to or less than 5") | Sq. Ft. | 14 |
| Cleaning Bridge Seats | Sq. Ft. | 243 |
| Concrete Sealer | Sq. Ft. | 243 |

BILL OF MATERIAL
(SN 095-0062)

| ITEM | UNIT | TOTAL |
|--|---------|-------|
| Structural Repair of Concrete (Depth equal to or less than 5") | Sq. Ft. | 14 |
| Cleaning Bridge Seats | Sq. Ft. | 243 |
| Concrete Sealer | Sq. Ft. | 243 |



EAST ABUTMENT - SN 095-0061 (EB)



EAST ABUTMENT - SN 095-0062 (WB)

- Notes:
- Hatched area indicates approximate area of Structural Repair of Concrete. Exact repairs are to be determined by the Engineer.
 - All existing abutment seats shall be cleaned & sealed. Work will be paid for as Cleaning Bridge Seats & Bridge Seat Sealer.

ABUTMENT CONCRETE REPAIRS
FAI 64 OVER
CNIC RAILROAD
FAI ROUTE 64 SECTION 95-6VB-1
WASHINGTON COUNTY
STATION 3263+73.50
STRUCTURE NO. 095-0061 (EB)
STRUCTURE NO. 095-0062 (WB)