

EAST ABUT. NB LANES

EAST ABUT. SB LANES

<u>LEGEND</u>

Denotes Structural Repair of Concrete (Depth Equal to or Less Than 5")



Denotes Concrete Removal

<u>NOTES</u>

- Cross hatched area indicates Concrete Removal. See Sheet 38 of 45 for concrete removal details.
- Existing Reinforcement which extends into the removal areas is to be preserved, cleaned and incorporated into the new construction in accordance with Section 501.03 of the Standard Specifications. Cost included in CONCRETE REMOVAL.

BILL OF MATERIAL

Item	Unit	Total
Structural Repair of Concrete (Depth Equal to or Less Than 5")	Sq. Ft.	14

CEC	Cummins Engineering Corporation		
Civil and Structural Engineering			

;	JOB	= 2265.1	DESIGNED	-	AAN	REVISED	-
ing	FILE =	0540053_0054-72E10-33-AbutRep.dgn	CHECKED	-	MDC	REVISED	-
ion	DATE	= 9/9/2011	DRAWN	-	MFC	REVISED	-
			CHECKED	-	MDC	REVISED	-
			1 0				

CONCRETE REPAIRS AT ABUTMENTS	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.	
STRUCTURE NO. 054-0053 (NB) & 054-0054 (SB)	55	D6 LOGAN CO. BR 2011	LOGAN	224	149	
31NOUTUNE NO. 037-0033 (ND) & 037-0037 (3D)		CONTRACT NO. 72E10				
SHEET NO 33 of 45 SHEETS	THE THOUGHT FED. ALD DOORST					