


DATE	NO.	BY	CHKD.	APP.
FAI 74	*	MCLEAN	160	102
REV. NO.	DATE	BY	CHKD.	APP.


Sheet 3
of 4 Sheets

• 57-20(1) & (57-4,5,6)RS-3


CONTRACT NO. 70505




WEST ABUTMENT
(Looking West)
(North End)
SN 057-0047 (EB)




EAST ELEVATION
(Looking West)
PIER 6
SN 057-0047 (EB)



EAST SLOPEWALL
(Looking East)
SN 057-0047 (EB)



WEST SLOPEWALL
(Looking West)
SN 057-0047 (EB)



EAST ABUTMENT
(Looking East)
SN 057-0047 (EB)

DESIGNED	JDA
CHECKED	JKC
DRAWN	NET
CHECKED	JDA

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Structural Repair of Concrete (Depth Equal to or Less Than 5')	Sq. Ft.	48
Slopewall Removal	Sq. Yd.	7.1
Slopewall, 4 Inch	Sq. Yd.	7.1

LEGEND

- Structural Repair of Concrete (Depth Equal to or Less Than 5')
- Slopewall Removal Slopewall, 4 Inch

PIER, ABUTMENT, AND SLOPEWALL REPAIR
F.A.I. ROUTE 74 OVER U.S. 51
SECTION 57-20(1) & (57-4,5,6)RS-3
MCLEAN COUNTY
SN 057-0047 (EB)
SN 057-0048 (WB)
STA. 719+63.58