

STATE OF ILLINOIS  
DEPARTMENT OF TRANSPORTATION

Various Routes  
OVD SIN STR REP & REPL 2006-9  
Various Counties  
Sheet 41 of 89  
Contract Number 44904

District 4  
Schedule of Locations for Truss Repair & Replacement

Location No.:	4-01	State I.D. No.:	4S090I474R012.7				
County:	Tazewell	Route:	I-474	M.P.:	12.7	Direction:	EB
Description of Work	Unit	Quantity					
REMOVE & RE-ERECT OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00					
REMOVE CONCRETE FOUNDATION OVERHEAD	EACH	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	10.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
PAINT OVERHEAD SIGN SUPPORT	EACH	2.00					
REPLACE / TIGHTEN CLIP PER SIGN	EACH	1.00					
FURNISH & INSTALL WALKWAY TIE DOWN BOLT	EACH	1.00					
DRILLED SHAFT CONCRETE FOUNDATION	CU YD	21.50					
RELOCATE ELECTRIC SERVICE	EACH	1.00					
OVERHEAD SIGN STRUCTURE WALKWAY	FOOT	68.00					
REMOVE & RE-ERECT OVERHEAD SIGN END SUPPORT	EACH	2.00					
DISCONNECT/RECONNECT ELECTRIC SERVICE	EACH	1.00					

Location No.:	4-05	State I.D. No.:	4S090I474R012.2				
County:	Tazewell	Route:	I-474	M.P.:	12.2	Direction:	EB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	4.00					
REPAIR CONCRETE FOUNDATION FOR OVERHEAD SIGN STRUCTURE	EACH	2.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	9.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					
FURNISH & INSTALL INTERNAL TRUSS CLAMP	EACH	1.00					
PAINT OVERHEAD SIGN SUPPORT	EACH	2.00					
REPLACE U-BOLT	EACH	12.00					

Location No.:	4-02	State I.D. No.:	4C072I474L003.41				
County:	Peoria	Route:	I-474	M.P.:	3.41	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	1.00					
REPAIR CONCRETE FOUNDATION FOR OVERHEAD SIGN STRUCTURE	EACH	1.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	4.00					
PAINT OVERHEAD SIGN SUPPORT	EACH	1.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					

Location No.:	4-03	State I.D. No.:	4C090S116L005.9				
County:	Tazewell	Route:	IL 116	M.P.:	5.9	Direction:	WB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	1.00					
TIGHTEN CANTILEVER CONNECTION	EACH	2.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	5.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					

Location No.:	4-04	State I.D. No.:	4C072U024R022.76				
County:	Peoria	Route:	US - 24	M.P.:	22.76	Direction:	EB
Description of Work	Unit	Quantity					
OVERHEAD SIGN SUPPORT GROUT REPAIR	EACH	1.00					
TIGHTEN CANTILEVER CONNECTION	EACH	2.00					
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	5.00					
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00					
FURNISH & INSTALL INTERNAL TRUSS DAMPER	EACH	1.00					