



Structural Repair of Concrete (Depth Equal to or Less than 5'')

Epoxy Crack Injection


## USER NAME = DESIGNED - J.Z. REVISED REVISED CHECKED - J.A.Z. E.E.J. REVISED PLOT DATE = DATE REVISED 5/17/2013

**DEPARTMENT OF TRANSPORTATION** 

WINGWALL REMOVAL & REPAIRS II STRUCTURE NO. 016-1149 SHEET NO. S36 OF 50 SHEETS


COUNTY TOTAL SHEET NO.

COOK 137 95 SECTION COUNTY 94 1920-B CONTRACT NO. 60J15



NORTHEAST WINGWALL ELEVATION

39'-72"



## NOTE

\*Epoxy grout d<sub>21</sub>(E) bars in 12" (min.) drilled holes according to Article 584 of the Standard Specifications.

**GR**@EF

STATE OF ILLINOIS