

PIER NO. 14 - ELEVATION - LEFT COLUMN

Column Surface Shown Unfolded



PIER COLUMN - PLAN

Looking North



PIER NO. 14 - ELEVATION - RIGHT COLUMN

Column Surface Shown Unfolded

REPAIRS LIST - PIER 14 - COLUMNS

I.D.	Description	Pay Item	Units	Quantity
112	Map Cracking	Concrete Sealer	SQ. FT.	249.9
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-



CONCRETE SEALER

DESIGNED -	EXAMINED	DATE -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	REPAIRS TO – PIER NUMBER 14 – COLUMNS STRUCTURE NO. 060–0255 SHEET NO. 39 OF 48 SHEETS
CHECKED -	ENGINEER OF STRUCTURAL SERVICES			
DRAWN Rod	PASSED			
CHECKED MNM	ENGINEER OF BRIDGES AND STRUCTURES			

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
304	1008-1DS-1	MADISON	58	49
		CONTRACT NO. 76E73		
		ILLINOIS FED. AID PROJECT		

© Copyright Hanson Professional Services Inc. 2012

hcfln00028 10/1/2012 12:09:07 PM
N:\jobs\HOOD\WORK\CAD\SHEETS\S6R00255-76E73-039-Pier-14_Column_Repairs.dgn