



BILL OF MATERIAL

Item	Unit	Total
Stone Riprap, Class A3	Sq. Yd.	12
Filter Fabric	Sq. Yd.	12
Controlled Low-Strength Material	Cu. Yd.	4
Concrete Joint Sealer	Foot	77
Slope Wall Removal	Sq. Yd.	4

NOTE:
Removal of existing low strength material at Southwest Wingwall shall be paid for as "Slopewall Removal".

3/25/2013 3:55:31 PM - G:\S1\12\0001\Bridges\CAD\Drawings\Bridges_0224\0600224-76F10-12-S_Slope_Repair.dgn

FILE NAME = 0600224-76F10-12-S_Slope_Repair.dgn

USER NAME = gshawley	DESIGNED - SDG	REVISED -
PLOT SCALE = 1/8" = 1' / in.	CHECKED - FAS	REVISED -
PLOT DATE = 3/25/2013	DRAWN - DMG	REVISED -
	CHECKED - SDG	REVISED -

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**SOUTH SLOPE REPAIRS
STRUCTURE NO. 060-0224NB**

SHEET NO. 12 OF 13 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
255	60-(8,9) RS-1	MADISON	206	195
				CONTRACT NO. 76F10
ILLINOIS FED. AID PROJECT				

