



Illinois Department of Transportation

2300 South Dirksen Parkway / Springfield, Illinois / 62764

February 24, 2025

SUBJECT FAP Route 870 (IL-53)
Project NHPP-V2QK(631)
Section FAP 0870 22 BJ2
DuPage County
Contract No. 62T31
Item No. 22, March 7th, 2025 Letting
Addendum A

NOTICE TO PROSPECTIVE BIDDERS:

Attached is an addendum to the plans or proposal. This addendum involves revised and/or added material.

1. Revised the Schedule of Prices.
2. Revised page ii of the Table of Contents of the Special Provisions.
3. Added page 117 to the Special Provisions.
4. Revised sheets 2, 5, 12 & 13 of the plans.

Prime contractors must utilize the enclosed material when preparing their bid and must include any changes to the Schedule of Prices in their bid.

Very truly yours,

A handwritten signature in black ink, appearing to read 'Jack A. Elston'.

Jack A. Elston, P.E.
Bureau Chief, Design and Environment

MTS

PREFORMED PLASTIC PAVEMENT MARKING (BDE)	82
REMOVAL AND DISPOSAL OF REGULATED SUBSTANCES (BDE)	83
SHORT TERM AND TEMPORARY PAVEMENT MARKINGS (BDE).....	84
SOURCE OF SUPPLY AND QUALITY REQUIREMENTS (BDE)	87
STEEL COST ADJUSTMENT (BDE).....	88
SUBCONTRACTOR AND DBE PAYMENT REPORTING (BDE)	90
SUBCONTRACTOR MOBILIZATION PAYMENTS (BDE)	91
SUBMISSION OF BIDDERS LIST INFORMATION (BDE).....	91
SUBMISSION OF PAYROLL RECORDS (BDE)	92
VEHICLE AND EQUIPMENT WARNING LIGHTS (BDE)	93
WEEKLY DBE TRUCKING REPORTS (BDE).....	93
WORK ZONE TRAFFIC CONTROL DEVICES (BDE)	93
SECTION 404 PERMIT CONDITIONS	96
GUARDRAIL POST REPAIR	117

Revised 2/24/25

GUARDRAIL POST REPAIR

This work shall be done in accordance with Sections 630, 631, 632, 633, and 701.17(f) of the Standard Specifications and as specified herein.

Description. When the guardrail post has been damaged, the Contractor shall remove and replace the steel post and wood blockout. When the condition of the guardrail post is still usable, the Contractor may replace the wood blockout in lieu of replacing the entire post. The Engineer will make the determination of the condition of the existing post.

Method of Measurement. This work will be measured for payment, complete in place, in units of each for each post and/or blockout replaced.

Basis of Payment. This work will be paid for at the contract unit price per each for GUARDRAIL POST REPAIR

Added 2/24/24