


±0.02(0.5)

SECTION A-A

General notes:

- Coldmilling shall consist of two processes: Cutting with carbide teeth mounted on a rotating drum, and planing with a moldboard mounted immediately behind the cutting drum.
- 2. Other similar patterns will be acceptable if they consist of a smooth, flat, planed surface interspersed with a pattern of discontinuous longitudinal striations.



All dimensions are in inches (millimeters) unless otherwise noted.

| O1-01-97 | RENUM. C-104.01, NEW REVISION BOX | T.P. | SECTION | COUNTY | SHEET | SHE