





## STRUCTURAL REPAIR

Cost included in Structural Repair of Concrete (Depth <5")

PATCH	STATION	AREA			
NUMBER		SQ FT			
1	48+80	6.0			
2	49+34	12.0			
3	49+73	3.0			
4	49+85	3.0			
5	50+42	3.0			
6	51+17	5.0			
	Total	32.0			

## NORTH PARAPET Looking North

TILE NAME =	USER NAME = swortzrw	DESIGNED -	REVISED -		STRUCTURAL REPAIR - PARAPET SN 058-0097		F.A.I. RTE.	SECTION	COUNTY TOTAL SHEET NO.
::\pw_work\PWIDOT\SWARTZRW\dms37779\ka	-enbridge.dgn	DRAWN -	REVISED -	STATE OF ILLINOIS			72	66(B,HVB,HB-1)BR	MACON 83 71
	PLOT SCALE = 20.0000 '/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION					CONTRACT NO. 74343
	PLOT DATE = 9/28/2009	DATE -	REVISED -		SCALE: N/A	SHEET NO. 6 OF 17 SHEETS STA. TO STA.	FED. ROA	D DIST. NO.   ILLINOIS FED. AI	AID PROJECT