

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

ROUTE	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
I-24	*	MASSAC	48	9
FED. ROAD DIST. NO. 7		ILLINOIS		

* D-9 BRIDGE PAINTING FY 05-2
CONTRACT NO. 98882

At each pier shown in the table below, the bottom flange at each existing new bearing shall be cleaned on the top, bottom, and side surfaces above the bearing and extending 3" past the bearing. This area shall be cleaned per Modified SP3 and Penetrating Epoxy sealer, Epoxy Mastic spot coat, and Polyurethane final coat shall be applied according to the requirements of Paint System 2.

BOTTOM FLANGE AT PIER BEARINGS

Bridge No.	Structure	Pier
1	064-0020	2
2	064-0021	2
3	064-0030	1
4	064-0031	1
* 7	064-0034	2

* ALL STRUCTURAL STEEL IS PAINTED ON BRIDGE NO. 7, 064-0034