



PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SQ YD	SQ YD	SQ YD
1	2.0 x 6.0			12.0
2	8.0 x 6.0			48.0
3	4.0 x 4.0			16.0
4	2.0 x 6.0			12.0
5	2.0 x 2.0		4.0	
6	2.0 x 6.0			12.0
7	2.0 x 6.0			12.0
8	2.0 x 6.0			12.0
	TOTAL	0	4	124

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SQ YD	SQ YD	SQ YD
	PARTIAL DEPTH			
	ESTIMATED			
	USE	23	SQ YD	
	FULL DEPTH, TYPE 1			
	4 / 9 =	0.4		
	USE	1	SQ YD	
	FULL DEPTH, TYPE 2			
	124 / 9 =	13.8		
	USE	14	SQ YD	

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SQ YD	SQ YD	SQ YD

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SQ YD	SQ YD	SQ YD

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SQ YD	SQ YD	SQ YD

THE LOCATIONS AND SIZES SHOWN GRAPHICALLY ABOVE ARE APPROXIMATE. SEE THIS TABLE FOR ACTUAL SIZES.

**PATCHING LEGEND**  
(FOR INFORMATION ONLY)

PARTIAL DEPTH

FULL DEPTH

DATE OF SURVEY: 07/07/09  
SURVEY BY: M. ALLEN, A. RING  
METHOD OF SURVEY: VISUAL

BRIDGE DECK PATCHING  
LAWRENCE COUNTY  
US 50 EBL OVER TR 262  
2.4 MILE EAST  
AIRPORT INTERCHANGE  
SN 051-0022

022