



MISSOURI BRIDGE APPROACH SLAB



REPAIRS LIST - MISSOURI APPROACH SLAB

I.D.	Description	Pay Item	Units	Quantity
122	Spalled Concrete Curb	Structural Repair of Concrete (Depth equal to or less than 5 Inches)	SQ. FT.	3.0
139	1/8" Slab Crack West Bound Lanes	Epoxy Crack Injection	FOOT	25
140	1/4" Slab Crack West Bound Lanes	Epoxy Crack Injection	FOOT	25
141	3/8" Slab Crack West Bound Lanes	Epoxy Crack Injection	FOOT	30

DESIGNED -	EXAMINED _____ DATE -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	REPAIRS TO - MISSOURI APPROACH SLAB STRUCTURE NO. 060-0255		F.A.P. RTE. 304	SECTION 100B-1DS-1	COUNTY MADISON	TOTAL SHEETS 58	SHEET NO. 57	
CHECKED -	PASSED _____		SHEET NO. 47 OF 48 SHEETS		ILLINOIS FED. AID PROJECT					
DRAWN Rod	ENGINEER OF STRUCTURAL SERVICES									
CHECKED MNM	ENGINEER OF BRIDGES AND STRUCTURES									