## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION € Pier 1 -- Brg. € Pier 2 ---€ Pier 3 --€ Brg. S. Abut. N. Abut. 15'-2" ---- Beam 9 Beam 12 -Temporary shoring may be required to facilitate Temporary shoring is required for alignment of existing splice. Use 12"x12" Beam 9. See table for reactions. Timbers or HP's to be paid for as Temporary Remove and replace slopewall. Shoring and Cribbing. Remove and replace if required. Cost included with slopewall, if required. Cost included with **ELEVATION** Temporary Shoring and Cribbing Temporary Shoring and Cribbing. 40'-4" Span 1 57′-8" Span 2 57'-8" Span 3 40'-4" Span 4 - € Brg. S. Abut. © Splice 2 - 18'-4" /8'-4" N. Abut. € Splice 1 -C Pier 1 € Splice 3 --± 14'-0" € Pier 2 -.2). 3 (4) (5) ·B) 9 --(D) (A) · 10)· Beam at 5'-= 15'-· (11)· (A)— - € Existing splice to be removed PLAN (A) Existing Beams to be replaced. Existing Beam to be straightened. Remove and replace existing diaphragm. Remove and replace bottom clip L's. REACTION TABLE AT SPAN I TEMPORARY SHORING 12.5 25.6 (k) 7.7 Imp.(k) Total (k) 45.8

081-004625

S RUCTURAL

Expires: November 30, 2008

Contract Number: 68803 \( \Delta \text{D4MCHD2008} \)

## GENERAL NOTES

All structural steel shall conform to AASHTO Classification M-270 Gr. 36, unless otherwise noted.

The Contractor shall provide support and/or shoring systems for the slab and beam in the area of existing beam removal. See Special Provisions "Temporary Shoring and Cribbing" and "Temporary Slab Support System."

After the new beam is in its final position and/or beam straightening operations have been completed, the Engineer in the field shall check to see that the top flange is tight against the slab. If not, the Contractor shall inject epoxy between the existing concrete deck and the top flange of the beam. See Special Provision "Epoxy Injection".

The existing structural steel coating contains lead. The Contractor shall take appropriate precautions to deal with the presence of lead on this project.

The Inorganic Zinc Rich Primer / Acrylic / Acrylic Paint System shall be used for shop and field painting of new structural steel except where otherwise noted. The color of the final finish coat shall be Interstate Green, Munsell No. 7.56 4/8. See Special Provision "Cleaning and Painting New Metal Structures".

Grind existing nicks, gauges and shallow cracks in the damaged beams as detailed. Grinding shall be done parallel to the longitudinal axis of the member. Ground surfaces shall be inspected for cracks using dye penetrant or magnetic particle testing prior to initiating any beam straightening operations. Any cracks that cannot be removed by grinding approximately  $^{\rm I}_4$ " deep shall be identified and reported to the Bureau of Bridges and Structures for further disposition. Ground surfaces shall be spot cleaned and painted with an aluminum epoxy mastic primer followed by a finish coat to match the color of the existing beam. Cost of grinding, testing and spot painting included with Beam Straightening.

Plan dimensions and details relative to existing plans are subject to routine variations. The Contractor shall field verify existing dimensions and details affecting new construction and make necessary approved adjustments prior to construction or ordering of materials. Such variations shall not be cause for additional compensation for a change in scope of the work, however, the Contractor will be paid for the quantity actually furnished based upon the unit price bid for the work.

Cost of removal and re-installation of all members necessary to complete the work as detailed on the plans and as specified in the Special Provisions shall be included with Furnishing and Erecting Structural Steel.

Existing structural steel that will be in contact with new structural steel shall be cleaned and painted prior to erection as required by the Special Provision "Cleaning and Painting Contact Surface Areas of Existing Steel Structures".

Load carrying components designated "NTR" shall conform to the Supplemental Requirements for Notch Toughness, Zone 2.

If the analysis submitted to the Contractor for the jacking/temporary support system to be used shows temporary stiffeners are required to prevent web crippling or buckling, the stiffeners shall be steel and bolted to the web. If stiffeners are not required, hardwood timbers shall be installed tightly between the top and bottom flange to prevent flange rotation.

## TOTAL BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Concrete Removal	Cu. Yd.	1.3
Concrete Superstructure	Cu. Yd.	1.3
Furnishing and Erecting Structural Steel	Pound	14,220
Temporary Slab Support System	L.S.	1
Beam Straightening	L.S.	1
Temporary Shoring and Cribbing	L.S.	1
Structural Steel Removal	Pound	14,220

PLAN AND ELEVATION
F.A.I. RT. 74
TAZEWELL COUNTY
SN 090-0091

SLT-94-001-07

DESIGNED Adrian T. Halloway

CHECKED ATH 578

..\projects\mac00034\0900091.dgn 4/15/2008 9:53:58 AM